

Site Visit Call Report

Call Report No: CRN-089 | Status: **Approved**

1. CUSTOMER INFORMATION

Name of the customer:	David Ochieng Oluoch
Salaried/Consultancy/Business:	Salaried
Project Name:	Home Build
Date & time of site visit:	10 Jun 2026, 15:04
Designation/name of the person met at the site:	Clients' Wife
Amounts Breakdown	
BQ amount:	KES 12,600,000
Construction loan amount:	KES 10,350,000
Customer's contribution:	KES 2,600,000
Drawn Funds to Date:	
No drawdowns recorded	
Sub-total Drawn: KES.	0
Undrawn funds to date:	KES 0

2. ADDITIONAL INFORMATION

Brief profile of the customer/facility (Construction/Buy & Build/Equity Release):	
Proposed home build	
Details of the Site	
Exact location:	Bypass, Thika
House located along:	Bypass, Thika
Site Pin:	-1.28535363, 36.82176364
Security details:	045213
Plot / LR No.	045213

3. PROJECT INFORMATION

Site Visit Objectives	
Objective 1: Confirm progress on site and level of work done	
Done	
Objective 2: Confirm status of the building including taking note of any visible defects	
Done	
Objective 3: Take note of materials stored on site	
Done	
Works Complete	Suspended gypsum finishes Floor screeding
Works Ongoing	None
Materials Found on Site	Crown paint
Defects Noted on Site	None
Drawdown Request No.	x
Drawdown KES Amount	KES 3,520,000

4. DOCUMENTS SUBMITTED

Document	Submitted
QS Valuation	Yes
Interim Certificate	Yes
Customer Instruction Letter	Yes
Contractor's Progress Report	No
Contractor's Invoice	No

5. SIGN-OFF

Prepared By	Shallot Damary
Signature	S.D
Date of Preparation	3 Jun 2026, 03:00


Authorised by:

Eric Mewa

Designation:

Quantity Surveyor

PROGRESS PHOTOS



MATERIALS ON SITE

