

Site Visit Call Report

Call Report No: CRN-053 | Status: **Approved**

1. CUSTOMER INFORMATION

Name of the customer:	Simon Kiprono Bii
Salaried/Consultancy/Business:	Salaried
Project Name:	Home Residence
Date & time of site visit:	2026-04-17T18:06
Designation/name of person met:	Simon's Wife
Amounts Breakdown	
BQ amount:	KES 25,000,000.00
Construction loan amount:	KES 25,000,000.00
Customer's contribution:	KES 2,500,000.00
Drawdown Funds to Date:	
Drawdown 1:	5,000,000.00
Drawdown 2:	7,500,000.00
Sub-total:	KES 5,000,000.00
Undrawn funds to date:	KES 12,500,000.00

2. ADDITIONAL INFORMATION

Brief profile of the customer:	Customer is requesting funds to build a house
Details of the Site	
Exact location:	JujaFarm
House located along:	JKUAT entrance road - Thika Highway
Site Pin:	-1.2852596673696424, 36.821616193398135

Security details:	1222
Plot/LR No.:	1222

3. PROJECT INFORMATION

Site Visit Objectives	
Objective 1: Progress	Foundation done Wall done Perimeter Wall done
Objective 2: Defects	None
Objective 3: Materials	Sand Cement Bricks
Works Complete:	Foundation Ground floor Wall
Works Ongoing:	First floor Installation of windows and doors
Materials Found on Site:	Sand Cement Bricks
Defects Noted on Site:	None
Drawdown Request No.:	xxx
Drawdown KES Amount:	KES 1,500,001.00

4. DOCUMENTS SUBMITTED

QS Valuation	Yes
Interim Certificate	Yes
Customer Instruction Letter	Yes
Contractor's Progress Report	No
Contractor's Invoice	No

5. SIGN-OFF

Prepared By:	Michael Mwai
Signature:	Michael Mwai
Date of Preparation:	17/04/2026

Authorised by:	Designation:

PROGRESS PHOTOS

MATERIALS ON SITE