

Site Visit Call Report

Call Report No: CRN-073 | Status: **Draft**

1. CUSTOMER INFORMATION

Name of the customer:	Jeniffer Chebet
Salaried/Consultancy/Business:	Business
Project Name:	Wabera Office Complex
Date & time of site visit:	2026-05-06T12:27
Designation/name of person met:	Jeniffer Chebet
Amounts Breakdown	
BQ amount:	KES 25,600,000.00
Construction loan amount:	KES 25,600,000.00
Customer's contribution:	KES 5,000,000.00
Drawdown Funds to Date:	
Drawdown 1:	5,600,000.00
Drawdown 2:	9,700,000.00
Drawdown 3:	2,500,000.00
Sub-total:	KES 17,800,000.00
Undrawn funds to date:	KES 7,800,000.00

2. ADDITIONAL INFORMATION

Brief profile of the customer:	Customer requesting funds to expand the business complex
Details of the Site	
Exact location:	Wabera, Kabete
House located along:	Wabera Street

Site Pin:	None
Security details:	LR No: 1564
Plot/LR No.:	None

3. PROJECT INFORMATION

Site Visit Objectives	
Objective 1: Progress	Foundation done Ground floor done First floor done
Objective 2: Defects	None
Objective 3: Materials	Sand Bricks Cement
Works Complete:	Foundation done Ground floor done First floor done
Works Ongoing:	Second Floor done Tiles installation
Materials Found on Site:	Cement Sand Ballast
Defects Noted on Site:	None
Drawdown Request No.:	xxxx
Drawdown KES Amount:	KES 5,000,000.00

4. DOCUMENTS SUBMITTED

QS Valuation	Yes
Interim Certificate	Yes
Customer Instruction Letter	Yes
Contractor's Progress Report	No
Contractor's Invoice	No

5. SIGN-OFF

Prepared By:	Shallot Damary
Signature:	Shallot Damary
Date of Preparation:	06/05/2026

Authorised by:	Designation:

PROGRESS PHOTOS

MATERIALS ON SITE