

5S Visual Audit – Before and After

Rev. 0

Date: 25.04.2025

Location: Label printing station – production floor, hall 4.

BEFORE



Before:
The desk and equipment are covered in dust and dirt. The bins are not labeled, and there are unnecessary items on and around the desk. There's an unused monitor on the desk.

AFTER



After:
Unnecessary items were removed from the desk and its surroundings. The bins were labeled according to their purpose. The entire desk and equipment were thoroughly cleaned. The login password was attached to the monitor.