

**MFE SERVICES SDN. BHD.** (952723-P)

No. 2339, Jalan Raja, Mukim Sungai Raya, 84300 Muar, Johor Darul Ta'zim.
Tel : 06-985 6988 / 985 8709 · Fax : 06-985 9806 · Email : mfetsb@gmail.com

Job Ref.	SV-20260820-9001
Issued	2026-09-23

FIRE SYSTEM SERVICE REPORT

FIRE FIGHTING & PROTECTION SYSTEM — MAINTENANCE, INSPECTION & TESTING

CLIENT	Demo CO2 Multi-Zone Client		
SITE / ADDRESS	Primary Service Site — 44 Frozen Road		
TELEPHONE / FAX	03-222	CONTACT PERSON	
DATE OF SERVICE	2026-08-20	ARRIVAL / DEPARTURE	
SERVICE CALL NO.		CONTRACT NO.	C-44
FREQUENCY	Quarterly	SERVICE STATUS	☒ COMPLETED ☐ TO BE CONTINUED
TEST LEADER	Alice Tan	TECHNICIANS	Alice Tan

FIRE FIGHTING & PROTECTION SYSTEMS SERVICED

☐ Automatic Sprinkler System	☐ Hose Reel System	☐ Fire Alarm / Detector System	☐ Hydrant System
☐ Portable Fire Extinguisher	☐ Dry / Wet Riser System	☒ CO2 Fire Extinguisher System	☐ Wet Chemical System
☐ FM 200 System	☐ Smoke Ventilation System	☐ Fire Intercom System	☐ Fire Rated Roller Shutter

WE HEREBY CONFIRM THAT THE ATTACHED RECORDS ARE TRUE AND CORRECT AS AT THE TIME OF INSPECTION / TESTING.

SERVICED BY — MFE SERVICES SDN. BHD.	VERIFIED BY — MFE SERVICES SDN. BHD.	CONFIRMED BY — CUSTOMER
Alice Tan Team: Signature · Date: 2026-08-20	 Name, Signature & Company Stamp · Date:	 Name, Signature & Company Stamp · Date:

Customer Satisfaction / Comment	☐ Excellent	☐ Satisfactory	☐ Not Satisfactory	Comment:
---------------------------------	------------------------------------	---------------------------------------	---	----------

NOTE :-

1. All fire systems listed above were tested and inspected on the date of service. Detailed results are recorded on the following pages.
2. Should any abnormal condition occur which might cause further damage to the customer's systems or threaten human safety or the environment, the customer agrees to call MFE immediately for necessary action.
3. Rectification works, parts replacement, piping and wiring works found necessary during this service are quoted and charged separately.
4. MFE is not responsible for any area, room or device that was not made accessible for inspection or testing on the date of service.

S	SUMMARY OF TESTING One line per system inspected. The condition is the overall result of that system; details are on the page shown.	DATE OF SERVICE 2026-08-20
----------	--	--------------------------------------

NO.	SYSTEM / TEST DESCRIPTION	LOCATION / UNIT	PAGE	FREQUENCY	CONDITION	MAIN FINDING
1	CO2 FIRE EXTINGUISHER SYSTEM	Zone 1 / Room A	3	Quarterly	GOOD CONDITIONS	—
2	CO2 FIRE EXTINGUISHER SYSTEM	Zone 1 / Room B	6	Quarterly	GOOD CONDITIONS	—
3	CO2 FIRE EXTINGUISHER SYSTEM	Zone 1 / Room C	9	Quarterly	GOOD CONDITIONS	—
4	CO2 FIRE EXTINGUISHER SYSTEM	Zone 1 / Room D	12	Quarterly	GOOD CONDITIONS	—
5	CO2 FIRE EXTINGUISHER SYSTEM	Zone 2 / Room E	15	Quarterly	GOOD CONDITIONS	—
6	CO2 FIRE EXTINGUISHER SYSTEM	Zone 3 / Room F	18	Quarterly	GOOD CONDITIONS	—

CONDITION INDICATOR

GOOD CONDITIONS	All items in good working condition; system ready for use.
REFER DETAIL PAGE	Defect found and rectified / minor defect; system usable during a fire emergency. See detail page.
FAILED	Defect found that affects the system. Rectification required; see detail page.

RESULT SYMBOLS (DETAIL PAGES)

✓ GOOD	In good working condition / Baik
✗ NOT GOOD	In poor working condition / Tidak Memuaskan
○ COMPLETE REPAIR	Defect rectified on site / Siap Baik Pulih
– N/A	No need checking / Tidak Berkaitan

ADVICE TO CUSTOMER :-

1. Replace fire alarm panel and pump starter batteries every 2 years or when capacity test fails, using the same ampere-hour rating.
2. Do not block fire protection equipment, alarm devices, exit doors, fire lift lobbies, staircases or escape routes. Do not padlock exit doors.
3. Emergency lights and KELUAR signs must be kept in working condition.
4. Do not use fire system water (hose reel, hydrant, riser, fire tank) except for fire fighting.
5. Do not isolate or switch off any fire alarm panel, pump set or suppression panel without informing MFE.
6. After any renovation shut-down, ensure all control valves are returned to the OPEN position.
7. Refill or replace any portable fire extinguisher immediately after use.
8. Contact MFE at 06-985 6988 for any complaint about this service.

1	CO2 FIRE EXTINGUISHER SYSTEM Zone 1 / Room A	SYSTEM CONDITION GOOD CONDITIONS
---	--	--

CO2 FIRE EXTINGUISHER SYSTEM

NO	INSPECTION & TEST	REQ / UNIT	READING	RESULT
1	Detector Rows 1 - Remarks			
2	Detector Rows 1 - Row Uuid		f2000000-0000-4000-8000-000000000500	
3	Detector Rows 1 - Location		Room A	
4	Detector Rows 1 - Alarm Zone		Zone	
5	Detector Rows 1 - Display Sequence		1	
6	Detector Rows 1 - Heat Detector Status		Normal	
7	Detector Rows 1 - Smoke Detector Status		Not recorded	
8	Physical Outlook - Alarm Bell - Result			✓ GOOD
9	Physical Outlook - Alarm Bell - Remarks			
10	Physical Outlook - Co2 Cylinder - Result			✓ GOOD
11	Physical Outlook - Co2 Cylinder - Remarks			
12	Physical Outlook - Pilot Cylinder - Result			✓ GOOD
13	Physical Outlook - Pilot Cylinder - Remarks			
14	Physical Outlook - Discharge Nozzles - Result			✓ GOOD
15	Physical Outlook - Discharge Nozzles - Remarks			
16	Physical Outlook - Electric Actuator - Result			✓ GOOD
17	Physical Outlook - Electric Actuator - Remarks			
18	Physical Outlook - High Pressure Hose - Result			✓ GOOD
19	Physical Outlook - High Pressure Hose - Remarks			
20	Physical Outlook - Manual Release Key - Result			✓ GOOD
21	Physical Outlook - Manual Release Key - Remarks			
22	Physical Outlook - Manual Pull Station - Result			✓ GOOD

1	CO2 FIRE EXTINGUISHER SYSTEM (continued) Zone 1 / Room A	SYSTEM CONDITION GOOD CONDITIONS
---	--	--

NO	INSPECTION & TEST	REQ / UNIT	READING	RESULT
23	Physical Outlook - Manual Pull Station - Remarks			
24	Physical Outlook - Twin Flashing Light - Result			✓ GOOD
25	Physical Outlook - Twin Flashing Light - Remarks			
26	Physical Outlook - 24v Dc Tripping Device - Result			✓ GOOD
27	Physical Outlook - 24v Dc Tripping Device - Remarks			
28	Main Function Keys - Evacuate - Result			✓ GOOD
29	Main Function Keys - Evacuate - Remarks			
30	Main Function Keys - Ac Supply - Result			✓ GOOD
31	Main Function Keys - Ac Supply - Remarks			
32	Main Function Keys - Dc Supply - Result			✓ GOOD
33	Main Function Keys - Dc Supply - Remarks			
34	Main Function Keys - Lamp Test - Result			✓ GOOD
35	Main Function Keys - Lamp Test - Remarks			
36	Main Function Keys - Main Alarm Reset - Result			✓ GOOD
37	Main Function Keys - Main Alarm Reset - Remarks			
38	Main Function Keys - Signal Alarm To Mfap - Result			✓ GOOD
39	Main Function Keys - Signal Alarm To Mfap - Remarks			
40	Charger And Batteries - Battery - Result			✓ GOOD
41	Charger And Batteries - Battery - Remarks			
42	Charger And Batteries - Charger - Result			✓ GOOD
43	Charger And Batteries - Charger - Remarks			
44	Charger And Batteries - Main Supply - Result			✓ GOOD
45	Charger And Batteries - Main Supply - Remarks			

1	CO2 FIRE EXTINGUISHER SYSTEM (continued) Zone 1 / Room A	SYSTEM CONDITION GOOD CONDITIONS
---	---	-------------------------------------

NO	INSPECTION & TEST	REQ / UNIT	READING	RESULT
46	Control Panel Location		Control Room	

REMARK : No defects found.

COMMENTS PostgreSQL accepted history

INSPECTION DATE	2026-08-20	INSPECTED BY	Alice Tan	
INITIAL				

2	CO2 FIRE EXTINGUISHER SYSTEM Zone 1 / Room B	SYSTEM CONDITION GOOD CONDITIONS
---	--	--

CO2 FIRE EXTINGUISHER SYSTEM

NO	INSPECTION & TEST	REQ / UNIT	READING	RESULT
1	Detector Rows 1 - Remarks			
2	Detector Rows 1 - Row Uuid		f2000000-0000-4000-8000-0000000000501	
3	Detector Rows 1 - Location		Room B	
4	Detector Rows 1 - Alarm Zone		Zone	
5	Detector Rows 1 - Display Sequence		1	
6	Detector Rows 1 - Heat Detector Status		Normal	
7	Detector Rows 1 - Smoke Detector Status		Not recorded	
8	Physical Outlook - Alarm Bell - Result			✓ GOOD
9	Physical Outlook - Alarm Bell - Remarks			
10	Physical Outlook - Co2 Cylinder - Result			✓ GOOD
11	Physical Outlook - Co2 Cylinder - Remarks			
12	Physical Outlook - Pilot Cylinder - Result			✓ GOOD
13	Physical Outlook - Pilot Cylinder - Remarks			
14	Physical Outlook - Discharge Nozzles - Result			✓ GOOD
15	Physical Outlook - Discharge Nozzles - Remarks			
16	Physical Outlook - Electric Actuator - Result			✓ GOOD
17	Physical Outlook - Electric Actuator - Remarks			
18	Physical Outlook - High Pressure Hose - Result			✓ GOOD
19	Physical Outlook - High Pressure Hose - Remarks			
20	Physical Outlook - Manual Release Key - Result			✓ GOOD
21	Physical Outlook - Manual Release Key - Remarks			
22	Physical Outlook - Manual Pull Station - Result			✓ GOOD

2	CO2 FIRE EXTINGUISHER SYSTEM (continued) Zone 1 / Room B	SYSTEM CONDITION GOOD CONDITIONS
---	--	--

NO	INSPECTION & TEST	REQ / UNIT	READING	RESULT
23	Physical Outlook - Manual Pull Station - Remarks			
24	Physical Outlook - Twin Flashing Light - Result			✓ GOOD
25	Physical Outlook - Twin Flashing Light - Remarks			
26	Physical Outlook - 24v Dc Tripping Device - Result			✓ GOOD
27	Physical Outlook - 24v Dc Tripping Device - Remarks			
28	Main Function Keys - Evacuate - Result			✓ GOOD
29	Main Function Keys - Evacuate - Remarks			
30	Main Function Keys - Ac Supply - Result			✓ GOOD
31	Main Function Keys - Ac Supply - Remarks			
32	Main Function Keys - Dc Supply - Result			✓ GOOD
33	Main Function Keys - Dc Supply - Remarks			
34	Main Function Keys - Lamp Test - Result			✓ GOOD
35	Main Function Keys - Lamp Test - Remarks			
36	Main Function Keys - Main Alarm Reset - Result			✓ GOOD
37	Main Function Keys - Main Alarm Reset - Remarks			
38	Main Function Keys - Signal Alarm To Mfap - Result			✓ GOOD
39	Main Function Keys - Signal Alarm To Mfap - Remarks			
40	Charger And Batteries - Battery - Result			✓ GOOD
41	Charger And Batteries - Battery - Remarks			
42	Charger And Batteries - Charger - Result			✓ GOOD
43	Charger And Batteries - Charger - Remarks			
44	Charger And Batteries - Main Supply - Result			✓ GOOD
45	Charger And Batteries - Main Supply - Remarks			

2	CO2 FIRE EXTINGUISHER SYSTEM (continued) Zone 1 / Room B	SYSTEM CONDITION GOOD CONDITIONS
---	---	-------------------------------------

NO	INSPECTION & TEST	REQ / UNIT	READING	RESULT
46	Control Panel Location		Control Room	

REMARK :
No defects found.

COMMENTS
PostgreSQL accepted history

INSPECTION DATE	2026-08-20	INSPECTED BY	Alice Tan	
INITIAL				

3	CO2 FIRE EXTINGUISHER SYSTEM			SYSTEM CONDITION GOOD CONDITIONS
	Zone 1 / Room C			

CO2 FIRE EXTINGUISHER SYSTEM

NO	INSPECTION & TEST	REQ / UNIT	READING	RESULT
1	Detector Rows 1 - Remarks			
2	Detector Rows 1 - Row Uuid		f2000000-0000-4000-8000-000000000502	
3	Detector Rows 1 - Location		Room C	
4	Detector Rows 1 - Alarm Zone		Zone	
5	Detector Rows 1 - Display Sequence		1	
6	Detector Rows 1 - Heat Detector Status		Normal	
7	Detector Rows 1 - Smoke Detector Status		Not recorded	
8	Physical Outlook - Alarm Bell - Result			✓ GOOD
9	Physical Outlook - Alarm Bell - Remarks			
10	Physical Outlook - Co2 Cylinder - Result			✓ GOOD
11	Physical Outlook - Co2 Cylinder - Remarks			
12	Physical Outlook - Pilot Cylinder - Result			✓ GOOD
13	Physical Outlook - Pilot Cylinder - Remarks			
14	Physical Outlook - Discharge Nozzles - Result			✓ GOOD
15	Physical Outlook - Discharge Nozzles - Remarks			
16	Physical Outlook - Electric Actuator - Result			✓ GOOD
17	Physical Outlook - Electric Actuator - Remarks			
18	Physical Outlook - High Pressure Hose - Result			✓ GOOD
19	Physical Outlook - High Pressure Hose - Remarks			
20	Physical Outlook - Manual Release Key - Result			✓ GOOD
21	Physical Outlook - Manual Release Key - Remarks			
22	Physical Outlook - Manual Pull Station - Result			✓ GOOD

3	CO2 FIRE EXTINGUISHER SYSTEM (continued) Zone 1 / Room C	SYSTEM CONDITION GOOD CONDITIONS
---	--	--

NO	INSPECTION & TEST	REQ / UNIT	READING	RESULT
23	Physical Outlook - Manual Pull Station - Remarks			
24	Physical Outlook - Twin Flashing Light - Result			✓ GOOD
25	Physical Outlook - Twin Flashing Light - Remarks			
26	Physical Outlook - 24v Dc Tripping Device - Result			✓ GOOD
27	Physical Outlook - 24v Dc Tripping Device - Remarks			
28	Main Function Keys - Evacuate - Result			✓ GOOD
29	Main Function Keys - Evacuate - Remarks			
30	Main Function Keys - Ac Supply - Result			✓ GOOD
31	Main Function Keys - Ac Supply - Remarks			
32	Main Function Keys - Dc Supply - Result			✓ GOOD
33	Main Function Keys - Dc Supply - Remarks			
34	Main Function Keys - Lamp Test - Result			✓ GOOD
35	Main Function Keys - Lamp Test - Remarks			
36	Main Function Keys - Main Alarm Reset - Result			✓ GOOD
37	Main Function Keys - Main Alarm Reset - Remarks			
38	Main Function Keys - Signal Alarm To Mfap - Result			✓ GOOD
39	Main Function Keys - Signal Alarm To Mfap - Remarks			
40	Charger And Batteries - Battery - Result			✓ GOOD
41	Charger And Batteries - Battery - Remarks			
42	Charger And Batteries - Charger - Result			✓ GOOD
43	Charger And Batteries - Charger - Remarks			
44	Charger And Batteries - Main Supply - Result			✓ GOOD
45	Charger And Batteries - Main Supply - Remarks			

3	CO2 FIRE EXTINGUISHER SYSTEM (continued) Zone 1 / Room C	SYSTEM CONDITION GOOD CONDITIONS
---	---	-------------------------------------

NO	INSPECTION & TEST	REQ / UNIT	READING	RESULT
46	Control Panel Location		Control Room	

REMARK :
No defects found.

COMMENTS
PostgreSQL accepted history

INSPECTION DATE	2026-08-20	INSPECTED BY	Alice Tan	
INITIAL				

4	CO2 FIRE EXTINGUISHER SYSTEM Zone 1 / Room D	SYSTEM CONDITION GOOD CONDITIONS
---	--	--

CO2 FIRE EXTINGUISHER SYSTEM

NO	INSPECTION & TEST	REQ / UNIT	READING	RESULT
1	Detector Rows 1 - Remarks			
2	Detector Rows 1 - Row Uuid		f2000000-0000-4000-8000-000000000503	
3	Detector Rows 1 - Location		Room D	
4	Detector Rows 1 - Alarm Zone		Zone	
5	Detector Rows 1 - Display Sequence		1	
6	Detector Rows 1 - Heat Detector Status		Normal	
7	Detector Rows 1 - Smoke Detector Status		Not recorded	
8	Physical Outlook - Alarm Bell - Result			✓ GOOD
9	Physical Outlook - Alarm Bell - Remarks			
10	Physical Outlook - Co2 Cylinder - Result			✓ GOOD
11	Physical Outlook - Co2 Cylinder - Remarks			
12	Physical Outlook - Pilot Cylinder - Result			✓ GOOD
13	Physical Outlook - Pilot Cylinder - Remarks			
14	Physical Outlook - Discharge Nozzles - Result			✓ GOOD
15	Physical Outlook - Discharge Nozzles - Remarks			
16	Physical Outlook - Electric Actuator - Result			✓ GOOD
17	Physical Outlook - Electric Actuator - Remarks			
18	Physical Outlook - High Pressure Hose - Result			✓ GOOD
19	Physical Outlook - High Pressure Hose - Remarks			
20	Physical Outlook - Manual Release Key - Result			✓ GOOD
21	Physical Outlook - Manual Release Key - Remarks			
22	Physical Outlook - Manual Pull Station - Result			✓ GOOD

4	CO2 FIRE EXTINGUISHER SYSTEM (continued) Zone 1 / Room D	SYSTEM CONDITION GOOD CONDITIONS
---	--	--

NO	INSPECTION & TEST	REQ / UNIT	READING	RESULT
23	Physical Outlook - Manual Pull Station - Remarks			
24	Physical Outlook - Twin Flashing Light - Result			✓ GOOD
25	Physical Outlook - Twin Flashing Light - Remarks			
26	Physical Outlook - 24v Dc Tripping Device - Result			✓ GOOD
27	Physical Outlook - 24v Dc Tripping Device - Remarks			
28	Main Function Keys - Evacuate - Result			✓ GOOD
29	Main Function Keys - Evacuate - Remarks			
30	Main Function Keys - Ac Supply - Result			✓ GOOD
31	Main Function Keys - Ac Supply - Remarks			
32	Main Function Keys - Dc Supply - Result			✓ GOOD
33	Main Function Keys - Dc Supply - Remarks			
34	Main Function Keys - Lamp Test - Result			✓ GOOD
35	Main Function Keys - Lamp Test - Remarks			
36	Main Function Keys - Main Alarm Reset - Result			✓ GOOD
37	Main Function Keys - Main Alarm Reset - Remarks			
38	Main Function Keys - Signal Alarm To Mfap - Result			✓ GOOD
39	Main Function Keys - Signal Alarm To Mfap - Remarks			
40	Charger And Batteries - Battery - Result			✓ GOOD
41	Charger And Batteries - Battery - Remarks			
42	Charger And Batteries - Charger - Result			✓ GOOD
43	Charger And Batteries - Charger - Remarks			
44	Charger And Batteries - Main Supply - Result			✓ GOOD
45	Charger And Batteries - Main Supply - Remarks			

4	CO2 FIRE EXTINGUISHER SYSTEM (continued) Zone 1 / Room D	SYSTEM CONDITION GOOD CONDITIONS
---	---	-------------------------------------

NO	INSPECTION & TEST	REQ / UNIT	READING	RESULT
46	Control Panel Location		Control Room	

REMARK :
No defects found.

COMMENTS
PostgreSQL accepted history

INSPECTION DATE	2026-08-20	INSPECTED BY	Alice Tan	
INITIAL				

5	CO2 FIRE EXTINGUISHER SYSTEM Zone 2 / Room E	SYSTEM CONDITION GOOD CONDITIONS
---	--	--

CO2 FIRE EXTINGUISHER SYSTEM

NO	INSPECTION & TEST	REQ / UNIT	READING	RESULT
1	Detector Rows 1 - Remarks			
2	Detector Rows 1 - Row Uuid		f2000000-0000-4000-8000-000000000504	
3	Detector Rows 1 - Location		Room E	
4	Detector Rows 1 - Alarm Zone		Zone	
5	Detector Rows 1 - Display Sequence		1	
6	Detector Rows 1 - Heat Detector Status		Normal	
7	Detector Rows 1 - Smoke Detector Status		Not recorded	
8	Physical Outlook - Alarm Bell - Result			✓ GOOD
9	Physical Outlook - Alarm Bell - Remarks			
10	Physical Outlook - Co2 Cylinder - Result			✓ GOOD
11	Physical Outlook - Co2 Cylinder - Remarks			
12	Physical Outlook - Pilot Cylinder - Result			✓ GOOD
13	Physical Outlook - Pilot Cylinder - Remarks			
14	Physical Outlook - Discharge Nozzles - Result			✓ GOOD
15	Physical Outlook - Discharge Nozzles - Remarks			
16	Physical Outlook - Electric Actuator - Result			✓ GOOD
17	Physical Outlook - Electric Actuator - Remarks			
18	Physical Outlook - High Pressure Hose - Result			✓ GOOD
19	Physical Outlook - High Pressure Hose - Remarks			
20	Physical Outlook - Manual Release Key - Result			✓ GOOD
21	Physical Outlook - Manual Release Key - Remarks			
22	Physical Outlook - Manual Pull Station - Result			✓ GOOD

5	CO2 FIRE EXTINGUISHER SYSTEM (continued) Zone 2 / Room E	SYSTEM CONDITION GOOD CONDITIONS
---	--	--

NO	INSPECTION & TEST	REQ / UNIT	READING	RESULT
23	Physical Outlook - Manual Pull Station - Remarks			
24	Physical Outlook - Twin Flashing Light - Result			✓ GOOD
25	Physical Outlook - Twin Flashing Light - Remarks			
26	Physical Outlook - 24v Dc Tripping Device - Result			✓ GOOD
27	Physical Outlook - 24v Dc Tripping Device - Remarks			
28	Main Function Keys - Evacuate - Result			✓ GOOD
29	Main Function Keys - Evacuate - Remarks			
30	Main Function Keys - Ac Supply - Result			✓ GOOD
31	Main Function Keys - Ac Supply - Remarks			
32	Main Function Keys - Dc Supply - Result			✓ GOOD
33	Main Function Keys - Dc Supply - Remarks			
34	Main Function Keys - Lamp Test - Result			✓ GOOD
35	Main Function Keys - Lamp Test - Remarks			
36	Main Function Keys - Main Alarm Reset - Result			✓ GOOD
37	Main Function Keys - Main Alarm Reset - Remarks			
38	Main Function Keys - Signal Alarm To Mfap - Result			✓ GOOD
39	Main Function Keys - Signal Alarm To Mfap - Remarks			
40	Charger And Batteries - Battery - Result			✓ GOOD
41	Charger And Batteries - Battery - Remarks			
42	Charger And Batteries - Charger - Result			✓ GOOD
43	Charger And Batteries - Charger - Remarks			
44	Charger And Batteries - Main Supply - Result			✓ GOOD
45	Charger And Batteries - Main Supply - Remarks			

5	CO2 FIRE EXTINGUISHER SYSTEM (continued) Zone 2 / Room E	SYSTEM CONDITION GOOD CONDITIONS
---	---	-------------------------------------

NO	INSPECTION & TEST	REQ / UNIT	READING	RESULT
46	Control Panel Location		Control Room	

REMARK : No defects found.

COMMENTS
PostgreSQL accepted history

INSPECTION DATE	2026-08-20	INSPECTED BY	Alice Tan	
INITIAL				

6	CO2 FIRE EXTINGUISHER SYSTEM Zone 3 / Room F	SYSTEM CONDITION GOOD CONDITIONS
---	--	--

CO2 FIRE EXTINGUISHER SYSTEM

NO	INSPECTION & TEST	REQ / UNIT	READING	RESULT
1	Detector Rows 1 - Remarks			
2	Detector Rows 1 - Row Uuid		f2000000-0000-4000-8000-000000000505	
3	Detector Rows 1 - Location		Room F	
4	Detector Rows 1 - Alarm Zone		Zone	
5	Detector Rows 1 - Display Sequence		1	
6	Detector Rows 1 - Heat Detector Status		Normal	
7	Detector Rows 1 - Smoke Detector Status		Not recorded	
8	Physical Outlook - Alarm Bell - Result			✓ GOOD
9	Physical Outlook - Alarm Bell - Remarks			
10	Physical Outlook - Co2 Cylinder - Result			✓ GOOD
11	Physical Outlook - Co2 Cylinder - Remarks			
12	Physical Outlook - Pilot Cylinder - Result			✓ GOOD
13	Physical Outlook - Pilot Cylinder - Remarks			
14	Physical Outlook - Discharge Nozzles - Result			✓ GOOD
15	Physical Outlook - Discharge Nozzles - Remarks			
16	Physical Outlook - Electric Actuator - Result			✓ GOOD
17	Physical Outlook - Electric Actuator - Remarks			
18	Physical Outlook - High Pressure Hose - Result			✓ GOOD
19	Physical Outlook - High Pressure Hose - Remarks			
20	Physical Outlook - Manual Release Key - Result			✓ GOOD
21	Physical Outlook - Manual Release Key - Remarks			
22	Physical Outlook - Manual Pull Station - Result			✓ GOOD

6	CO2 FIRE EXTINGUISHER SYSTEM (continued) Zone 3 / Room F	SYSTEM CONDITION GOOD CONDITIONS
---	--	--

NO	INSPECTION & TEST	REQ / UNIT	READING	RESULT
23	Physical Outlook - Manual Pull Station - Remarks			
24	Physical Outlook - Twin Flashing Light - Result			✓ GOOD
25	Physical Outlook - Twin Flashing Light - Remarks			
26	Physical Outlook - 24v Dc Tripping Device - Result			✓ GOOD
27	Physical Outlook - 24v Dc Tripping Device - Remarks			
28	Main Function Keys - Evacuate - Result			✓ GOOD
29	Main Function Keys - Evacuate - Remarks			
30	Main Function Keys - Ac Supply - Result			✓ GOOD
31	Main Function Keys - Ac Supply - Remarks			
32	Main Function Keys - Dc Supply - Result			✓ GOOD
33	Main Function Keys - Dc Supply - Remarks			
34	Main Function Keys - Lamp Test - Result			✓ GOOD
35	Main Function Keys - Lamp Test - Remarks			
36	Main Function Keys - Main Alarm Reset - Result			✓ GOOD
37	Main Function Keys - Main Alarm Reset - Remarks			
38	Main Function Keys - Signal Alarm To Mfap - Result			✓ GOOD
39	Main Function Keys - Signal Alarm To Mfap - Remarks			
40	Charger And Batteries - Battery - Result			✓ GOOD
41	Charger And Batteries - Battery - Remarks			
42	Charger And Batteries - Charger - Result			✓ GOOD
43	Charger And Batteries - Charger - Remarks			
44	Charger And Batteries - Main Supply - Result			✓ GOOD
45	Charger And Batteries - Main Supply - Remarks			

6	CO2 FIRE EXTINGUISHER SYSTEM (continued) Zone 3 / Room F	SYSTEM CONDITION GOOD CONDITIONS
---	---	-------------------------------------

NO	INSPECTION & TEST	REQ / UNIT	READING	RESULT
46	Control Panel Location		Control Room	

REMARK :
No defects found.

COMMENTS
PostgreSQL accepted history

INSPECTION DATE	2026-08-20	INSPECTED BY	Alice Tan	
INITIAL				

— END OF REPORT —