

North West Defects

Overgrown weeds all all over this side

South East Defects
1:75

No.	Description	Date

AUTODESK.		PROJECT Dullburn House	CLIENT				
	www.autodesk.com/revit		SHEET	Date 23/09/21 Drawn by	Project number Project Number DRWAING NUMBER	Scale (@ A3) 1 : 75	
	ODE STATUS	SUITABILITY DESCRIPTION	PURPOSE OF ISSUE	DEFECTS VIEW DULLBURN 2	Author Checked by Checker	A102	