

DAILY DRILLING OPERATIONS REPORT

Report Date: May 22, 2026

EXECUTIVE SUMMARY

Metric	Value
Total Active Rigs	10
Total Depth Drilled (m)	6,221.77
Total Intervals Drilled	1,000
Coal Intervals Identified	95
Unique Coal Seams	29
Average Depth per Rig (m)	622.18
Report Generation Time	23:06:41


KEY INSIGHTS

- **Top Performing Rig:** Rig_05 with 692.18m drilled
- **Most Common Lithology:** TUFF (11.1%)
- **Highest Quality Seam:** Seam_17 (CVAR: 7,283.58)
- **Lowest Quality Seam:** Seam_24 (CVAR: 4,273.00)

RIG PERFORMANCE SUMMARY

Comprehensive overview of drilling performance by rig.


RIG	Intervals	Depth (m)	Avg Depth/Interval
Rig_05	108	692.18	6.41
Rig_07	104	674.35	6.48
Rig_06	104	662.37	6.37
Rig_09	100	656.25	6.56
Rig_03	105	642.09	6.12
Rig_10	106	635.33	5.99
Rig_01	96	622.80	6.49
Rig_08	93	580.21	6.24
Rig_04	96	546.37	5.69
Rig_02	88	509.82	5.79




LITHOLOGY DISTRIBUTION ANALYSIS

Lithology	Interval Count	Percentage
TUFF	111	11.1%
CARB	109	10.9%
SS	106	10.6%
MS	100	10.0%
SILT	98	9.8%
CL	98	9.8%
SH	98	9.8%
CO	95	9.5%
SLT	93	9.3%
CB	92	9.2%

Lithology Distribution




Percentage Breakdown



COAL SEAM QUALITY RANKING


Seam Name	CVAR	TM (%)	TS (%)	ASH (%)
Seam_24	4,273.00	12.68	0.77	17.54
Seam_14	4,620.01	18.56	1.32	21.29
Seam_20	5,006.98	12.62	1.22	16.12
Seam_26	5,062.42	14.83	1.06	17.41
Seam_25	5,093.05	13.91	0.35	17.98
***	***	***	***	***
Seam_12	6,164.01	15.04	0.77	16.00
Seam_30	6,218.23	13.31	0.78	13.42
Seam_28	6,304.80	13.44	1.62	14.23
Seam_13	6,326.04	15.87	0.94	10.17
Seam_15	6,437.48	10.44	1.10	19.74
Seam_01	6,455.53	15.83	1.71	21.09
Seam_22	6,464.19	14.28	1.40	4.47
Seam_09	6,591.91	11.17	0.49	15.27
Seam_11	6,628.83	12.12	1.03	6.50
Seam_17	7,283.58	13.86	0.27	12.48

Top 5 (red) = Lowest CVAR | Bottom 10 (green) = Highest CVAR







COAL SEAM THICKNESS SUMMARY

Seam Name	Total (m)	Avg (m)	Count	Rigs
Seam_02	38.15	6.36	6	Rig_01, Rig_04, Rig_...
Seam_13	38.14	6.36	6	Rig_01, Rig_03, Rig_...
Seam_10	34.56	5.76	6	Rig_02, Rig_04, Rig_...
Seam_09	34.16	8.54	4	Rig_01, Rig_02, Rig_...
Seam_07	27.83	9.28	3	Rig_03, Rig_05, Rig_...
Seam_08	27.55	4.59	6	Rig_03, Rig_05, Rig_...
Seam_05	27.42	5.48	5	Rig_04, Rig_05, Rig_...
Seam_30	25.32	5.06	5	Rig_01, Rig_08, Rig_...
Seam_23	24.64	6.16	4	Rig_03, Rig_09, Rig_...
Seam_19	24.18	6.04	4	Rig_02, Rig_06, Rig_...
Seam_04	23.60	5.90	4	Rig_05, Rig_07, Rig_...
Seam_12	23.22	7.74	3	Rig_02, Rig_08, Rig_...
Seam_21	22.91	7.64	3	Rig_06, Rig_08, Rig_...
Seam_06	20.61	5.15	4	Rig_05, Rig_07
Seam_17	19.14	9.57	2	Rig_03, Rig_04



COAL QUALITY PARAMETERS



Classification: Premium (CVAR≥6500, Ash<15%) | Standard (CVAR≥5500) | Low (CVAR<5500)

DAILY OPERATIONS SUMMARY

OPERATIONAL HIGHLIGHTS

Total Depth: 6,221.77 meters across 10 rigs (avg 622.18m/rig).

Coal Discovery: 95 coal intervals across 29 distinct seams.

Geology: 10 lithology types, TUFF most prevalent at 11.1%.

Quality Range: CVAR 4,273.00 to 7,283.58.

RECOMMENDATIONS

Priority: Focus on Seam_17 and Seam_11 (highest CVAR).

Efficiency: Review Rig_05 practices for fleet implementation.

Quality: Consider blending for Seam_24 (lowest CVAR).

— END OF REPORT —
Generated 2026-05-22 23:06:44