



Relatório diário

CP020 · BBS Mexico · 5 de ago. de 2026

Registro operacional

Projeto CP020 · BBS Mexico	Cliente IMPC Gmbh
Data 5 de ago. de 2026	Trabalhador Gabriel Santos
Status Aprovado	Relacionado à segurança Sim
Planta / turno Plant 1 · First Shift (07:00 - 17:00)	Minutos de parada 0
Motivo de espera None · Normal continuous operation	

Resumo

Commissioned Allen Bradley ControlLogix safety zones and validated Siemens S7-1500 interlocks for Stations 10 to 14. Supervised trial production run with 0 safety incidents.

Tarefas concluídas

Safety circuit checkout, servo axis tuning, HMI alarm messaging verified

Problemas encontrados

Photoelectric sensor bracket on station 12 was misaligned

Ações corretivas

Re-aligned bracket and tightened mounting bolts; retested trigger window