



Relatório diário

CP020 · BBS Mexico · 5 de ago. de 2026

Registro operacional

Projeto

CP020 · BBS Mexico

Cliente

IMPC Gmbh

Data

5 de ago. de 2026

Trabalhador

Gabriel Santos

Status

Aprovado

Relacionado à segurança

Sim

Planta / turno

**Plant 1 · First Shift (07:00
- 17:00)**

Minutos de parada

0

Motivo de espera

**None · Normal continuous
operation**

Resumo

Commissioned Allen Bradley ControlLogix safety zones and validated Siemens S7-1500 interlocks for Stations 10 to 14. Supervised trial production run with 0 safety incidents.

Tarefas concluídas

Safety circuit checkout, servo axis tuning, HMI alarm messaging verified

Problemas encontrados

Photoelectric sensor bracket on station 12 was misaligned

Ações corretivas

Re-aligned bracket and tightened mounting bolts; retested trigger window