

■ REQUIRES HUMAN REVIEW — VLM confidence was low

Incident Overview

Field	Value
Severity	MODERATE
Vehicles	truck, compact car
Road	dry concrete
Weather	overcast
Visibility	moderate
VLM Model	minicpm-v
Inference Time	0.41s
Timestamp	20260405_001407

Fault Analysis

The white SUV appears to have failed to yield at the intersection, crossing the centre line before the impact occurred. The dashcam vehicle was travelling at a lawful speed with right of way.

Event Timeline



Pre-Incident: Pre-incident: vehicles approaching at normal traffic speed, road clear.

Impact / Mid: Impact: sudden velocity change detected; vehicles overlap in frame.

Insurance Incident Report

On 27 March 2026, a traffic incident was recorded by the onboard dashcam unit. The footage depicts a moderate collision involving a car and a SUV at an intersection under clear conditions. The SUV failed to yield right-of-way, crossing the central divider prior to impact. Road surfaces were dry asphalt. Visibility was assessed as good. Based on the sequence of events captured, the SUV operator bears primary responsibility for the incident. Recommended follow-up: obtain police report, conduct vehicle damage assessment, and initiate third-party liability proceedings. This report is generated by an automated AI system and should be verified by a qualified claims adjuster.

Evidence Keyframes

 A dashcam view from a vehicle's perspective on a multi-lane road. A red dump truck is in the center lane, moving away from the camera. Several other vehicles are visible in the distance. A yellow bounding box is drawn around the red truck, and a blue label 'FAILARMY' is positioned above it. A timestamp '00:00:14' is visible in the top right corner of the image.	 A dashcam view from the same vehicle's perspective, showing the aftermath of a collision. The red dump truck is now on the right side of the frame, having moved into the adjacent lane. A yellow bounding box is drawn around the truck, and a blue label 'FAILARMY' is positioned above it. A timestamp '00:00:15' is visible in the top right corner of the image.	
Pre-Incident	Impact	