

InspectAI — Property Condition Report

Report version 1 · Published 2026-09-14

24 Oak Street

24 Oak Street, Johannesburg, Gauteng — Main House

Inspection type: MOVE-OUT · Submitted 2026-09-14

Reviewed findings

General Wear LOW

Stub observation: routine wear recorded at checkpoint "Photograph the entrance door, front and edge".
Confidence 62% · 1 evidence item(s)

General Wear LOW · amended by landlord

Landlord corrected: pre-existing crack, 15cm. Verified against move-in report.
Confidence 62% · 1 evidence item(s)

General Wear LOW

Stub observation: routine wear recorded at checkpoint "Photograph the kitchen worktops and sink".
Confidence 62% · 1 evidence item(s)

General Wear LOW

Stub observation: routine wear recorded at checkpoint "Photograph inside the oven and hob".
Confidence 62% · 1 evidence item(s)

General Wear LOW

Stub observation: routine wear recorded at checkpoint "Photograph the bathroom basin, bath and shower".
Confidence 62% · 1 evidence item(s)

General Wear LOW

Stub observation: routine wear recorded at checkpoint "Photograph the walls in each bedroom".
Confidence 62% · 1 evidence item(s)

General Wear LOW

Stub observation: routine wear recorded at checkpoint "Photograph built-in cupboards, open".
Confidence 62% · 1 evidence item(s)

Analysis summary

Stub analysis: 8 routine-wear observation(s) recorded. All findings are advisory and require landlord review.

AI observations in this report are advisory only. Condition assessments and any related decisions are the responsibility of the reviewing landlord or property manager.

Published by Kutloano Yende <kutloano@yendeproperties.co.za> via InspectAI.

Reference: cmu1ql1f4000bzt76o9ncvv1