

Summary

February 23, 2021

1 Windowing study




Figure 1: battery study

1.1 Audio deck mic




Figure 2: no motors




Figure 3: motors




Figure 4: comparison raw




Figure 5: comparison

1.2 Measurement mic




Figure 6: no motors




Figure 7: motors




Figure 8: comparison raw




Figure 9: comparison