
frame_000 | +0.00s | SERVICE_INTERFACE_STOP


Original recorded image / display-only model projection



Saved native model geometry / independent local plan



This window only; tails not executed



frame_000 t0=+0.000s
Status: SERVICE_INTERFACE_STOP / block: SERVICE
Real requests: 1 | source: NO_NATIVE_OUTPUT
Attempt: 1 | actual server snapshot: UNKNOWN
Decision: NOT_REACHED | desired v: UNKNOWN
Stages: SERVICE=FAIL | BUSINESS_SCHEMA=NOT_REACHED | T1=NOT_REACHED | T2=NOT_REACHED | T3=NOT_REACHED | T4=NOT_REACHED | TURN_TASK=NOT_REACHED | ACCEPTOR=NOT_REACHED | EXECUTION=NOT_REACHED
Objects declared: UNKNOWN
T4 stage: NOT_REACHED | selected-plan T4: NOT_REACHED
Prefix consumed: False | clearance lower bound: None m
Prefix: NOT_EXECUTED | distance=None m
Prefix end speed: None m/s
Signed plan yaw: None deg | lateral=None m
Signed prefix yaw: None deg
Turn direction / road agreement: independent review pending.
Amplitude gate: plan >=5 deg and >=0.3m; prefix >=0.1 deg and >0.01m.
These are descriptive gates, not safety or correct-turn proof.
Image dots/line: display-only z=0 projection, not detection/GT.


Recorded observations, not observations caused by these plans. Each 2s plan and consumed 0.2s prefix starts independently; no stitched execution, real vehicle control or GT evaluation.

frame_001 | +0.50s | NOT_ATTEMPTED


Original recorded image / display-only model projection



Saved native model geometry / independent local plan



This window only; tails not executed



frame_001 t0=+0.500s
Status: NOT_ATTEMPTED / block: NONE
Real requests: 0 | source: NO_NATIVE_OUTPUT
Attempt: None | actual server snapshot: UNKNOWN
Decision: NOT_REACHED | desired v: UNKNOWN
Stages: SERVICE=NOT_REACHED | BUSINESS_SCHEMA=NOT_REACHED | T1=NOT_REACHED | T2=NOT_REACHED | T3=NOT_REACHED | T4=NOT_REACHED | TURN_TASK=NOT_REACHED | ACCEPTOR=NOT_REACHED | EXECUTION=NOT_REACHED
Objects declared: UNKNOWN
T4 stage: NOT_REACHED | selected-plan T4: NOT_REACHED
Prefix consumed: False | clearance lower bound: None m
Prefix: NOT_EXECUTED | distance=None m
Prefix end speed: None m/s
Signed plan yaw: None deg | lateral=None m
Signed prefix yaw: None deg
Turn direction / road agreement: independent review pending.
Amplitude gate: plan >=5 deg and >=0.3m; prefix >=0.1 deg and >0.01m.
These are descriptive gates, not safety or correct-turn proof.
Image dots/line: display-only z=0 projection, not detection/GT.


Recorded observations, not observations caused by these plans. Each 2s plan and consumed 0.2s prefix starts independently; no stitched execution, real vehicle control or GT evaluation.

frame_002 | +1.00s | NOT_ATTEMPTED


Original recorded image / display-only model projection



Saved native model geometry / independent local plan



This window only; tails not executed



frame_002 t0=+1.000s
Status: NOT_ATTEMPTED / block: NONE
Real requests: 0 | source: NO_NATIVE_OUTPUT
Attempt: None | actual server snapshot: UNKNOWN
Decision: NOT_REACHED | desired v: UNKNOWN
Stages: SERVICE=NOT_REACHED | BUSINESS_SCHEMA=NOT_REACHED | T1=NOT_REACHED | T2=NOT_REACHED | T3=NOT_REACHED | T4=NOT_REACHED | TURN_TASK=NOT_REACHED | ACCEPTOR=NOT_REACHED | EXECUTION=NOT_REACHED
Objects declared: UNKNOWN
T4 stage: NOT_REACHED | selected-plan T4: NOT_REACHED
Prefix consumed: False | clearance lower bound: None m
Prefix: NOT_EXECUTED | distance=None m
Prefix end speed: None m/s
Signed plan yaw: None deg | lateral=None m
Signed prefix yaw: None deg
Turn direction / road agreement: independent review pending.
Amplitude gate: plan >=5 deg and >=0.3m; prefix >=0.1 deg and >0.01m.
These are descriptive gates, not safety or correct-turn proof.
Image dots/line: display-only z=0 projection, not detection/GT.


Recorded observations, not observations caused by these plans. Each 2s plan and consumed 0.2s prefix starts independently; no stitched execution, real vehicle control or GT evaluation.

frame_003 | +1.50s | NOT_ATTEMPTED


Original recorded image / display-only model projection



Saved native model geometry / independent local plan



This window only; tails not executed



frame_003 t0=+1.500s
Status: NOT_ATTEMPTED / block: NONE
Real requests: 0 | source: NO_NATIVE_OUTPUT
Attempt: None | actual server snapshot: UNKNOWN
Decision: NOT_REACHED | desired v: UNKNOWN
Stages: SERVICE=NOT_REACHED | BUSINESS_SCHEMA=NOT_REACHED | T1=NOT_REACHED | T2=NOT_REACHED | T3=NOT_REACHED | T4=NOT_REACHED | TURN_TASK=NOT_REACHED | ACCEPTOR=NOT_REACHED | EXECUTION=NOT_REACHED
Objects declared: UNKNOWN
T4 stage: NOT_REACHED | selected-plan T4: NOT_REACHED
Prefix consumed: False | clearance lower bound: None m
Prefix: NOT_EXECUTED | distance=None m
Prefix end speed: None m/s
Signed plan yaw: None deg | lateral=None m
Signed prefix yaw: None deg
Turn direction / road agreement: independent review pending.
Amplitude gate: plan >=5 deg and >=0.3m; prefix >=0.1 deg and >0.01m.
These are descriptive gates, not safety or correct-turn proof.
Image dots/line: display-only z=0 projection, not detection/GT.


Recorded observations, not observations caused by these plans. Each 2s plan and consumed 0.2s prefix starts independently; no stitched execution, real vehicle control or GT evaluation.

frame_004 | +2.00s | NOT_ATTEMPTED


Original recorded image / display-only model projection



Saved native model geometry / independent local plan



This window only; tails not executed



frame_004 t0=+2.000s
Status: NOT_ATTEMPTED / block: NONE
Real requests: 0 | source: NO_NATIVE_OUTPUT
Attempt: None | actual server snapshot: UNKNOWN
Decision: NOT_REACHED | desired v: UNKNOWN
Stages: SERVICE=NOT_REACHED | BUSINESS_SCHEMA=NOT_REACHED | T1=NOT_REACHED | T2=NOT_REACHED | T3=NOT_REACHED | T4=NOT_REACHED | TURN_TASK=NOT_REACHED | ACCEPTOR=NOT_REACHED | EXECUTION=NOT_REACHED
Objects declared: UNKNOWN
T4 stage: NOT_REACHED | selected-plan T4: NOT_REACHED
Prefix consumed: False | clearance lower bound: None m
Prefix: NOT_EXECUTED | distance=None m
Prefix end speed: None m/s
Signed plan yaw: None deg | lateral=None m
Signed prefix yaw: None deg
Turn direction / road agreement: independent review pending.
Amplitude gate: plan >=5 deg and >=0.3m; prefix >=0.1 deg and >0.01m.
These are descriptive gates, not safety or correct-turn proof.
Image dots/line: display-only z=0 projection, not detection/GT.


Recorded observations, not observations caused by these plans. Each 2s plan and consumed 0.2s prefix starts independently; no stitched execution, real vehicle control or GT evaluation.

frame_005 | +2.50s | NOT_ATTEMPTED


Original recorded image / display-only model projection



Saved native model geometry / independent local plan



This window only; tails not executed



frame_005 t0=+2.500s
Status: NOT_ATTEMPTED / block: NONE
Real requests: 0 | source: NO_NATIVE_OUTPUT
Attempt: None | actual server snapshot: UNKNOWN
Decision: NOT_REACHED | desired v: UNKNOWN
Stages: SERVICE=NOT_REACHED | BUSINESS_SCHEMA=NOT_REACHED | T1=NOT_REACHED | T2=NOT_REACHED | T3=NOT_REACHED | T4=NOT_REACHED | TURN_TASK=NOT_REACHED | ACCEPTOR=NOT_REACHED | EXECUTION=NOT_REACHED
Objects declared: UNKNOWN
T4 stage: NOT_REACHED | selected-plan T4: NOT_REACHED
Prefix consumed: False | clearance lower bound: None m
Prefix: NOT_EXECUTED | distance=None m
Prefix end speed: None m/s
Signed plan yaw: None deg | lateral=None m
Signed prefix yaw: None deg
Turn direction / road agreement: independent review pending.
Amplitude gate: plan >=5 deg and >=0.3m; prefix >=0.1 deg and >0.01m.
These are descriptive gates, not safety or correct-turn proof.
Image dots/line: display-only z=0 projection, not detection/GT.

Recorded observations, not observations caused by these plans. Each 2s plan and consumed 0.2s prefix starts independently; no stitched execution, real vehicle control or GT evaluation.