

DAMAGESCOPE | SATELLITE DISASTER ASSESSMENT REPORT

JOB ID: d67d714f-2e44-4b0b-838b-df76b4b7d4c2 | TIMESTAMP: 2026-08-04 04:29:44 UTC | STATUS: COMPLETED

TACTICAL ASSESSMENT: LOW RISK GREEN ZONE - MINIMAL STRUCTURAL IMPACT

PRIMARY ACTION FOCUS: Standard Recovery & Documentation

Building Damage Severity Summary

Category	Building Count	Percentage
No Damage	9	100.0%
Minor Damage	0	0.0%
Major Damage	0	0.0%
Destroyed	0	0.0%
Total Detected	9	100.0%

Automated Disaster Recovery Action Directives

Directive #1: Conduct localized structural checks on flagged minor-damage buildings.
Directive #2: Allow resident re-entry under general caution.
Directive #3: Begin insurance claims processing and municipal assessment logging.

Satellite Imagery Comparison

Pre-Disaster Satellite Image

Post-Disaster Satellite Image

