

Task order

Service request	10893742: 12.09.2026 14:36
Address	Emännäntie 10 (M) 401, 40740 JYVÄSKYLÄ  Use of master key is permitted
Description	Oven is really dirty. Bathroom air valve not working, smells bad, blocked by dust & no circulation. One slat of the bed is broken.
Additional information	My room is 401/A
Urgency	Normal
Area of responsibility	Property maintenance
Service provider	 Soihitu Kiinteistöhuolto (/julmo#/services/mornkzcf)
Manager	 Soihitu Kiinteistöhuolto (/julmo#/services/mornkzcf)

Events



 12.09.2026 14:36 Task order
 12.09.2026 14:36 Room number: 401/1

Documents/photos





WhatsApp Image 2026-09-12 at 14.06.35.jpeg.jpg





WhatsApp Image 2026-09-12 at 14.02.04 (3).jpeg.jpg



WhatsApp Image 2026-09-12 at 14.02.03.jpeg.jpg





WhatsApp Image 2026-09-12 at 14.06.33.jpeg.jpg



WhatsApp Image 2026-09-12 at 14.02.04 (2).jpeg.jpg



WhatsApp Image 2026-09-12 at 14.02.04.jpeg.jpg