

Vehicle Inspection Report

Report ID: IR-2026-0610-001

Inspection Date: June 10, 2026

Inspector: Automated System

VEHICLE INFORMATION

Make/Model	Proton Saga 1.3A	License Plate	DBKL 1234
Mileage	29000 km	VIN	JT2B23EK30012345

INSPECTION SUMMARY

Category	Status	Remarks
Engine System	Pass	Running smoothly, no abnormal vibrations.
Brake System	Pass	Brake pad thickness within normal range.
Tires & Suspension	Pass	Front-right tire shows significant wear, replacement advised.
Electronics	Pass	Sensor readings nominal.

OVERALL ASSESSMENT & RECOMMENDATIONS

The vehicle is in good overall condition. However, it is recommended to replace the front-right tire to ensure safety. A four-wheel alignment check is advised post-replacement.