

Damaged Stock and Machinery List

Claim ID	PROP-B2B-2026-0417
Insured	Nordhafen Precision Parts GmbH
Document type	Inventory / stock list
Issued by	Nordhafen Precision Parts GmbH
Document date	15 May 2026
Loss location	Hafenstrasse 18, Building B, 30179 Hannover, Germany

Inventory valuation method stated by insured

The insured exported damaged stock and WIP from ERP system MFG-Pro on 15 May 2026. Values are standard manufacturing cost unless noted. The inventory sheet was prepared before a physical count was completed and before salvage bids were received.

Summary category	Gross claimed value	Estimated salvage	Net claimed value
Finished goods - Volta Pumps order VP-7712	EUR 284,600	EUR 31,000	EUR 253,600
Work in progress - CNC line 2	EUR 196,400	EUR 12,500	EUR 183,900
Raw aluminium blanks and inserts	EUR 111,200	EUR 37,000	EUR 74,200
Packaging, labels, customer-specific kits	EUR 38,100	EUR 1,000	EUR 37,100
Machinery / measuring equipment	EUR 441,900	EUR 15,000	EUR 426,900
Total listed	EUR 1,072,200	EUR 96,500	EUR 975,700

High-value line items

Item ID	Description	Qty	Gross EUR	Status / issue
VP-7712-FG-A	Finished pump housings, anodized, customer-specific packaging	2,400	214,800	Smoke odour in cartons; rework not yet tested.
VP-7712-FG-B	Pump housing lids, final inspection passed 10 May	1,800	69,800	Potential salvage after cleaning.
WIP-CNC2-183	Semi-finished aluminium blocks, operation 4 of 7	3,100	196,400	Water on pallets; oxidation risk.
RAW-AL-6082	Aluminium blanks 6082-T6	8,200 kg	111,200	Scrap value available.
MACH-MEAS-02	Zeiss measuring bench controller and guide rail	1	148,000	Engineer noted possible pre-loss corrosion.
CNC-CTRL-5X-A	Replacement controller and servo pack for CNC line 2	2	221,500	Quote pending; contamination assessment only.
FLT-CHG-48V	HanseLift charger and charging bench	1	15,400	May be cause item; preserve evidence.

Valuation and documentation issues

- ERP export uses standard cost, not actual replacement cost or net realizable value required by the policy.
- Several WIP items were on pallets in the packing area but may not have been physically wetted; contamination testing pending.
- The raw aluminium blanks have meaningful scrap value. The insured estimated salvage but no bid is attached.
- Two machinery items include full replacement cost although repair quotes and cleaning assessment are not complete.
- Finished goods for Volta Pumps may be rejected for customer quality reasons even if physically cleanable. Customer rejection letter not yet provided.

Physical count observations from adjuster assistant

Rack / area	Observation	Follow-up
A1-A3 finished goods	Cartons wet at floor level; upper cartons smoke-odour only.	Segregate by pallet and test cleaning.
A4-A5 labels and kits	Customer-specific labels curled from moisture.	Likely low salvage.
CNC line 2 staging	WIP trays partially uncovered; light soot film.	Confirm quantity versus ERP.
Raw material rack R7	Aluminium blanks dry above floor; water on lower pallet.	Scrap value to be credited.
Measuring bench	Guide rail brown staining, not clearly new.	Check pre-loss maintenance photos.

Inventory conclusion

The inventory list is useful as a gross exposure schedule but should not be treated as an agreed quantum. A coverage-adjusted valuation requires physical count, salvage bids, customer rejection evidence, repair-versus-replacement decisions, and policy valuation application.