Oak & Stone Maintenance

Oak Street apartment

Work handover

Client: Jordan Reed

Property: 24 Oak Street · Unit 3

Visit date: 1 October 2026

Recorded by: Alex Morgan

Issued: 1 October 2026 at 9:45 AM

Sample business · oak@example.com

Record summary

2 done · 0 open · 1 return visit

1 item needs a return visit

1 item is missing a required after photo


Agreed work

Replace the kitchen mixer, adjust the cabinet doors and reseal the sink edge.

1. Replace kitchen tap


Done · Kitchen

Installed the customer-supplied mixer. Checked connections and cleared the work area.



Before · Example image · Added 1 Oct 2026 at 9:45 AM

Illustrative fixture — initial condition



After · Example image · Added 1 Oct 2026 at 9:45 AM

Illustrative fixture — completed work

2. Adjust cabinet doors

Done · Kitchen

Doors aligned and hinges tightened.

3. Reseal the sink edge

Return visit · Kitchen

Required after photo not attached

Return after the customer removes the countertop items.

Visit notes

Sample job used to demonstrate the app. No real customer information.

Customer acknowledgment

No customer acknowledgment recorded. This is the contractor's work record.

About this record

This report records the information entered by its author. It is not a certified inspection or a guarantee that unrecorded defects are absent. Photo dates show when images were added to the notebook. A signature records in-person acknowledgment, not independently verified identity. Later changes are issued as a new version.