Northbridge Lettings

Check-out inspection report

Records the condition and cleanliness of the bedroom and bathroom at Flat 5, 55 Lantern Quay, Cedarford, ZZ2 4ZZ after the tenancy, with descriptions and photographic evidence of defects.

Check-out inspection. Appointment date: 5 January 2026. Assessor: Northbridge Lettings. Property: Flat 5, 55 Lantern Quay, Cedarford, ZZ2 4ZZ.

The report provides a room-by-room visual schedule of condition. Where no comment is made about an element or item, it is taken to be in good, clean, serviceable condition and without defects. Observed defects are described and supported by photographs. Material terms such as “silver”, “chrome” and “oak” describe appearance and may not identify the actual material. Items are described for identification; items are called new only in a new or newly refurbished building or while still in manufacturer wrapping. In an existing property, wear and tear is assumed unless otherwise noted.

Limitations: the assessor is not an expert in fabrics, woods, materials, antiques or similar items. The report does not necessarily identify structural defects, advise on repairs, or state repair costs. Fixtures and fittings are listed but may not have been tested. The inspection is visual and covers the inside of the main building and contents, plus a general inspection of the remainder of the building, including exterior cosmetic elements and permanent outbuildings. Inaccessible and loft areas are not inspected. Belongings left by the landlord in locked rooms or outbuildings are not inspected and remain the landlord’s responsibility. Items of little monetary value may be described generically.

Ownership: the report remains the property of the instructing party and must not be used without written permission.

Guidance: at the end of a tenancy, the property and contents are expected to be in a similar condition and state of cleanliness to that recorded before the tenancy. Damage considered beyond fair wear and tear may need repair or replacement, with the cost deducted from the tenant’s deposit; receipts should be retained and produced if required. If cleaning is unsatisfactory, a managing agent or landlord may instruct professional cleaners, with the cost deducted from the deposit; receipts should be retained. The property should be left tidy and thoroughly cleaned.

The report’s cleaning guidance says carpets should be professionally cleaned in accordance with the inventory or tenancy agreement, and vinyl or tile flooring should be clean and free from cracks or tears. Curtains should be professionally cleaned where required by the inventory or tenancy agreement. Decor should be in the same state and condition as at the start of the tenancy. Charges may apply for picture hooks, nails, screws or screw holes not removed or repaired satisfactorily; excessive marks and fingerprints should be removed. Fingerprints on walls and doors are considered a cleaning issue. Refrigerators and freezers should be defrosted, switched off and left open. Ovens, hobs, extractor units and microwaves should be cleaned of burnt-on deposits and grease, including doors and seals. Gardens, where applicable, should be left neat and tidy, with lawns cut, borders and planters weeded, hedges trimmed, and paths and patios weeded and swept.

The guidance states that smoke and carbon monoxide alarms were checked and working on the report date. The tenant is responsible for keeping them in working order during the tenancy; faults other than battery replacement should be reported immediately.

Condition glossary: Excellent means unused or new; Good means minor wear without obvious faults in appearance or function; Fair means wear or minor damage; Poor means extensive wear such as stains, marks, rips or chips; Unacceptable means not fit for purpose, such as being badly damaged or faulty.

Cleanliness glossary for inspection areas: Excellent means cleaned to a high standard; Good means cleaned to a good standard; Fair means cleaned to a fair standard; Poor means light

cleaning is required; Unacceptable means professional cleaning is required. For items, Fair, Poor and Unacceptable refer to the issues and photographs as applicable.

Detector check: tested — Yes. No general detector comments were recorded.

Bedroom description: door as per inventory. Ceiling as per inventory, including existing water-ingress staining. Lighting works as expected. Walls were scuffed and scratched at inventory; new staining was noted. Window and blinds are as per inventory. Flooring has pre-existing burn damage and multiple stains requiring professional cleaning. Mattress has staining not noted on the inventory. Wardrobe and television are as per inventory. Table missing. A radiator cover is stained.

Bathroom description: door, ceiling and lighting as per inventory. Plastic-clad walls are in fair condition. Bath requires cleaning for limescale and dirt; shower and bathing equipment and basin tap require limescale cleaning. Bath tap is dripping. Walls are in fair condition. Boxing requires repainting or repair due to water egress from the shower area. Shelving unit is burnt or stained. Toilet is in fair condition. Basin is damaged and plug is broken. Some waste items have been dumped. Light cleaning is required due to limescale.

Assessor declaration: the assessor confirms that the report reflects their assessment of the property. Assessor: Northbridge Lettings. Email: assessor@example.com. Signature received: 3 April 2025 15:51:25.

Inspection area	Condition	Cleanliness	Defects	Photos
Bedroom	Poor	Poor	8	35
Bathroom	Unacceptable	Poor	7	24

General detector details	Tested?	General detector comments
	Yes	

Area	Date	Condition	Cleanliness	Description and defects
Bedroom	5 January 2026	Poor	Poor	Door as per inventory. Ceiling as per inventory, including water-ingress staining. Lighting works as expected. Walls were scuffed and scratched at inventory; new staining noted. Window and blinds as per inventory. Flooring has pre-existing burn damage and multiple stains requiring professional cleaning. Mattress stained, not noted on inventory. Wardrobe and television as per inventory. Table missing. Stained radiator cover. Defects: stained radiator cover; stained or scuffed walls; carpet burn damage; carpet stains; evidence of water ingress to ceiling; stained mattress; dirty boxing; missing table and chair.
Bathroom	5 January 2026	Unacceptable	Poor	Door, ceiling and lighting as per inventory. Plastic-clad walls in fair condition. Bath requires cleaning for limescale and dirt. Shower and bathing equipment and basin tap require limescale cleaning. Bath tap dripping. Walls in fair condition. Boxing requires repainting or repair due to water egress from shower area. Shelving unit burnt or stained. Toilet in fair condition. Basin damaged and plug broken. Some waste items dumped. Light cleaning

Area	Date	Condition	Cleanliness	Description and defects
				required due to limescale. Defects: light cleaning required due to limescale; water damage to boxing and flooring; stained flooring; broken plug; dumped items; shelf defects; dripping bath tap.

Category	Rating	Meaning
Condition	Excellent	Unused or new condition.
Condition	Good	Minor signs of wear, but no obvious faults in appearance or functionality.
Condition	Fair	Signs of wear or minor damage present.
Condition	Poor	Extensive wear, for example stains, marks, rips or chips.
Condition	Unacceptable	Not fit for purpose in its present state, for example badly damaged or faulty.
Cleanliness	Excellent	Cleaned to a high standard.
Cleanliness	Good	Cleaned to a good standard.
Cleanliness	Fair	Cleaned to a fair standard.
Cleanliness	Poor	Light cleaning required.
Cleanliness	Unacceptable	Professional cleaning required.

Observations

- The bedroom was rated Poor for condition and Poor for cleanliness.
- The bathroom was rated Unacceptable for condition and Poor for cleanliness.
- The report records water-ingress staining on the bedroom ceiling and water damage to bathroom boxing and flooring.
- The report notes pre-existing bedroom burn damage to the carpet, as well as multiple carpet stains requiring professional cleaning.
- The report records a missing table and chair in the bedroom; the room description separately states that the table is missing.
- The bathroom defects include a broken plug, damaged basin, defective shelf, dripping bath tap, stained flooring, limescale and dumped waste items.
- The smoke and carbon monoxide detector check is recorded as tested: Yes.

Findings

- The report summary records 8 bedroom defects and 35 bedroom photographs.
- The report summary records 7 bathroom defects and 24 bathroom photographs.
- The bedroom defect list is: stained radiator cover; stained or scuffed walls; carpet burn damage; carpet stains; evidence of water ingress to ceiling; stained mattress; dirty boxing; missing table and chair.
- The bathroom defect list is: light cleaning required due to limescale; water damage to boxing and flooring; stained flooring; broken plug; dumped items; shelf defects; dripping bath tap.

Conclusions

- The check-out inspection identified substantial condition and cleaning issues in both inspected areas, with the bathroom condition rated Unacceptable and the bedroom condition rated Poor.
- The report provides visual evidence of the listed defects but does not provide repair advice or cost estimates.

Image evidence

Neutral image placeholder

Bedroom overview photographs (3): general views of the bedroom, including its door, ceiling, window, flooring and furnishings.

Neutral image placeholder

Bedroom radiator-cover photographs (2): show staining on the radiator cover.

Neutral image placeholder

Bedroom wall photographs (6): show stained or scuffed wall surfaces.

Neutral image placeholder

Bedroom carpet burn-damage photograph (1): close view documenting burn damage to the carpet.

Neutral image placeholder

Bedroom carpet-stain photographs (8): close views documenting multiple carpet stains.

Neutral image placeholder

Bedroom ceiling photograph (1): documents evidence of water ingress to the ceiling.

Neutral image placeholder

Bedroom mattress photographs (3): show staining on the mattress.

Neutral image placeholder

Bedroom boxing photographs (2): show dirty boxing.

Neutral image placeholder

Bathroom overview photographs (3): general views of the bathroom and its fixtures.

Neutral image placeholder

Bathroom limescale-cleaning photographs (4): show areas identified as requiring light cleaning due to limescale.

Neutral image placeholder

Bathroom water-damage photographs (7): document water damage to the boxing and flooring.

Neutral image placeholder

Bathroom flooring photographs (2): show stained flooring.

Neutral image placeholder

Bathroom plug photograph (1): documents the broken plug.

Neutral image placeholder

Bathroom dumped-items photographs (3): show waste items left in the bathroom.

Neutral image placeholder

Bathroom shelf photographs (3): document shelf defects.

Neutral image placeholder

Bathroom tap photograph (1): documents the dripping bath tap.