Northbridge Lettings

Property inspection report

Record the inspection condition and cleanliness of Flat 12, 162 Beacon Close, Cedarford, ZZ9 5ZZ, and identify any noted defects.

Inspection for Flat 12, 162 Beacon Close, Cedarford, ZZ9 5ZZ. Appointment date: 16 February 2024. Assessor: assessor named in the report. Agency: Northbridge Lettings.

The report provides an impartial, room-by-room schedule of condition for the main property features and any contents. Where the assessor makes no comment on an element or item, it is taken to be in good, clean, serviceable condition and without defects. Defects or elements in poor condition observed during inspection are to be identified in the narrative and evidenced with photographs.

Descriptions such as ‘silver’, ‘chrome’ and ‘oak’ refer to appearance and not necessarily the actual material. Listed items are described for identification. Items are described as new only when in a new or newly refurbished building, or still in manufacturer wrapping. In a property that is not new or newly refurbished, some wear and tear is assumed unless otherwise noted.

The report preparer is not an expert on fabrics, woods, materials, antiques or similar items. The report will not necessarily mention structural defects and does not advise on repairs or their cost. Fixtures and fittings are listed and described, but may not have been tested.

The assessor visually inspects the interior of the main building and contents, and generally inspects the remainder of the building, including exterior cosmetic elements and permanent outbuildings. Inaccessible areas and loft areas are not inspected. Belongings left by the landlord in a locked room or outbuildings are not inspected and remain the landlord’s responsibility. Items of little monetary value are listed and described generically.

The report remains the property of the instructing party and shall not be used without written permission.

At the end of the tenancy, the property and its contents are expected to be in a similar condition and state of cleanliness to that recorded before the tenancy began. Damage believed to exceed fair wear and tear may need repair or replacement, with the cost deducted from the tenant’s deposit. Receipts should be retained and produced if required.

If cleaning is unsatisfactory, a managing agent or landlord may instruct a professional cleaner; the cost if this will be deducted from the tenant’s deposit. Receipts should be retained where professional cleaners are used. Cleaning must be thorough and the property left tidy at the end of the tenancy.

Carpets should be professionally cleaned before the end of the tenancy in accordance with the inventory or tenancy agreement. Vinyl or tile flooring should be clean and free from cracks or tears. Curtains should be professionally cleaned in accordance with the inventory or tenancy agreement.

The decor should remain in the same state and condition as at the start of the tenancy. Charges may be incurred if picture hooks, nails, screws or screw holes are added and not removed or repaired satisfactorily. Excessive marks and fingerprints should be removed; fingerprints on walls and doors are considered a cleaning issue, although reasonable wear and tear is expected.

Refrigerators and freezers should be defrosted, switched off and left open to avoid smelling. Ovens, hobs, extractor units and microwaves should be cleaned thoroughly of burnt-on deposits and grease, including doors and seals. Gardens, where applicable, should be left neat and tidy, with lawns cut, borders and planters weeded, hedges trimmed, and pathways and patios weeded and swept.

Smoke and carbon monoxide alarms were checked and recorded as working on the report date. The tenant is responsible for keeping them in working order throughout the tenancy. Faults other than battery replacement should be reported immediately.

Assessor declaration: the report reflects the assessor's assessment of the property. Signature received 16 February 2024 at 16:32:45.

Section	Rating	Meaning
Inspection areas — condition	Excellent	Brand new property or recently refurbished area. No signs of damage.
Inspection areas — condition	Good	May have negligible signs of wear, but no serious faults in appearance or functionality.
Inspection areas — condition	Fair	Signs of wear/minor damage present. Small chips, marks and/or other imperfections present.
Inspection areas — condition	Poor	Showing extensive signs of wear. Large chips, marks and/or other defects that can be considered serious.
Inspection areas — condition	Unacceptable	Not fit for purpose. Extensively damaged and likely to need professional repair.
Inspection areas — cleanliness	Excellent	Immaculate. Cleaned to a professional standard.
Inspection areas — cleanliness	Good	May have some very minor dust or marks, but generally in a satisfactory state of cleanliness.
Inspection areas — cleanliness	Fair	Showing average signs of dust, dirt and/or marks. May benefit from light cleaning.
Inspection areas — cleanliness	Poor	Showing extensive signs of dust, dirt and/or marks. Requires cleaning to bring back to a satisfactory state.
Inspection areas — cleanliness	Unacceptable	Extremely dirty and not fit for purpose. Requires thorough cleaning to a professional standard.

Item	Result
Carbon monoxide detectors tested and working	Yes
Smoke / heat detectors tested and working	Yes
Evidence of smoking	No
Evidence of condensation	No
Evidence of damp	No
Evidence of non-tenants	No
Evidence of pets	Yes
Property generally maintained to a good standard	Yes

Inspection area	Condition	Cleanliness	Defects	Photos
Entrance/Hallway	Good	Good	0	0
Toilet	Good	Good	0	0

Inspection area	Condition	Cleanliness	Defects	Photos
Living Room	Good	Good	0	0
Kitchen	Good	Good	0	0
Utility Room	Good	Good	0	0
Stairs/Landing	Good	Good	0	0
Bathroom	Good	Good	0	0
Bedroom 1	Good	Good	1	0
Bedroom 2	Good	Good	0	0
Bedroom 3	Good	Good	0	0
En Suite	Good	Good	0	0

Inspection area	Entry	Date	Condition	Cleanliness	Description
Entrance/Hallway	General Overview	16 February 2024	Good	Good	
Toilet	General Overview	16 February 2024	Good	Good	
Living Room	General Overview	16 February 2024	Good	Good	
Kitchen	General Overview	16 February 2024	Good	Good	
Utility Room	General Overview	16 February 2024	Good	Good	Tenant's have installed a dog flap here.
Stairs/Landing	General Overview	16 February 2024	Good	Good	
Bathroom	General Overview	16 February 2024	Good	Good	
Bedroom 1	General Overview	16 February 2024	Good	Good	Downstairs front bedroom. Sticker type markings to w2 next to the window, look like the stickers from some command strips, tenant will need to remove and make good.
Bedroom 2	General Overview	16 February 2024	Good	Good	

Inspection area	Entry	Date	Condition	Cleanliness	Description
Bedroom 3	General Overview	16 February 2024	Good	Good	
En Suite	General Overview	16 February 2024	Good	Good	

Area	Entry	Condition	Cleanliness	Defect
Bedroom 1	General Overview	Good	Good	Sticker type markings to the wall next to the window, look like the stickers from some command strips; tenant will need to remove and make good.

Observations

- Overall condition was described as good.
- The tenants have a small dog and a fish tank.
- A dog flap has been installed in the back door, noted in the general comments and utility-room overview.
- The garden was described as being kept tidy.
- Bedroom 1 is described as the downstairs front bedroom. Sticker-type markings were noted on the wall beside the window, described as looking like stickers from command strips. The tenant was to remove them and make good.
- All 11 inspection areas were rated Good for condition and Good for cleanliness.
- Bedroom 1 was the only area with a recorded defect. The report summary records zero photos for every inspection area.

Findings

- Checklist: carbon monoxide detectors tested and working — Yes.
- Checklist: smoke / heat detectors tested and working — Yes.
- Checklist: evidence of smoking — No.
- Checklist: evidence of condensation — No.
- Checklist: evidence of damp — No.
- Checklist: evidence of non-tenants — No.
- Checklist: evidence of pets — Yes.
- Checklist: property generally maintained to a good standard — Yes.
- Bedroom 1 defect: sticker-type markings to the wall next to the window, apparently from command strips; tenant to remove and make good. Condition Good; cleanliness Good.

Conclusions

- The inspection recorded the property and all listed rooms as Good for condition and cleanliness.
- One defect was recorded: sticker-type marks on the Bedroom 1 wall beside the window, for the tenant to remove and make good.
- The report notes a dog flap installation and pets, while the checklist records no evidence of damp, condensation, smoking or non-tenants.

Image evidence

Neutral image placeholder

Exterior/frontage view of the property, including the front entrance and windows.