Northbridge Lettings

Check-out inspection report

Records the observed condition and cleanliness of the bedroom and bathroom at Flat 5, 55 Lantern Quay, Cedarford, ZZ2 4ZZ after the tenancy, with defect notes and photographs.

Appointment date: 5 January 2026. Assessor: Northbridge Lettings. Inspection: check-out.

The report describes the condition of the property room by room. Where no comment is made on an element or item, it is treated as being in good, clean, serviceable condition and without defects. Observed defects are described and evidenced with photographs.

The report is a visual inspection. Inaccessible and loft areas are not inspected. Fixtures and fittings may not have been tested. The report does not necessarily identify structural defects, provide repair advice or estimate repair costs. Descriptive material terms are used for appearance and identification, not necessarily to identify actual materials.

Guidance notes: At the end of a tenancy, the property and its contents are expected to be in a similar condition and state of cleanliness to the pre-tenancy report, allowing for fair wear and tear. Items damaged beyond fair wear and tear may need repair or replacement; receipts should be retained. If cleaning is unsatisfactory, a professional cleaner may be instructed. Cleaning should be thorough and the property left tidy. Carpets should be professionally cleaned in line with the inventory or tenancy agreement; vinyl or tile floors should be clean and free from cracks or tears. Decor should be returned to its recorded condition; excessive marks and fingerprints may be treated as a cleaning issue. Alarms are stated to have been checked and to be working as of the report date; faults other than battery replacement should be reported immediately.

Smoke and carbon monoxide detectors: tested — Yes. No general detector comments are recorded.

Bedroom inspection, dated 5 January 2026: condition Poor; cleanliness Poor. Door, ceiling, lighting, window, blinds, wardrobe and television were recorded as per inventory; the ceiling included a watermark. Lighting worked as expected. Walls were already scuffed and scratched at inventory, but the stain marks were new. Flooring had burn damage recorded as per inventory and multiple stains requiring professional cleaning. Mattress staining was not noted on the inventory. Table missing. Defects noted: stained radiator cover; stained/scuffed walls; burn damage to carpet; carpet stains; evidence of water ingress to ceiling; stained mattress; dirty boxing; missing table and chair.

Bathroom inspection, dated 5 January 2026: condition Unacceptable; cleanliness Poor. Door, ceiling and lighting were recorded as per inventory. Plastic-clad walls and other walls were in fair condition. Bath required cleaning for limescale and dirt; shower, bathing equipment and basin tap required limescale cleaning. Bath tap dripping. Boxing required repainting or repair due to water egress from the shower area. Shelving unit burnt or stained. Toilet was in fair condition; basin was damaged and plug broken. Some waste items had been dumped. Light cleaning was required due to limescale. Water damage was present on boxing and flooring; flooring was stained. Defects noted: light cleaning required due to limescale; water damage on boxing and flooring; stained flooring; broken plug; dumped items; shelf defects; dripping bath tap.

Summary of defects — Bedroom: condition Poor; cleanliness Poor. Stained radiator cover; stained/scuffed walls; burn damage to carpet; carpet stains; evidence of water ingress to ceiling; stained mattress; dirty boxing; missing table and chair.

Summary of defects — Bathroom: condition Unacceptable; cleanliness Poor. Light cleaning required due to limescale; water damage on boxing and flooring; stained flooring; broken plug; dumped items; shelf defects; dripping bath tap.

Assessor declaration: The assessor confirms that the report reflects their assessment of Flat 5, 55 Lantern Quay, Cedarford, ZZ2 4ZZ. Signature received: 3 April 2025 at 15:51:25. The contact

email is represented synthetically as assessor@example.com.

Section	Rating	Meaning
Inspection areas — condition	Excellent	Unused or new condition.
Inspection areas — condition	Good	Minor signs of wear, but no obvious faults in appearance or functionality.
Inspection areas — condition	Fair	Signs of wear or minor damage present.
Inspection areas — condition	Poor	Extensive wear, such as stains, marks, rips or chips.
Inspection areas — condition	Unacceptable	Not fit for purpose in present state, such as badly damaged or faulty.
Inspection areas — cleanliness	Excellent	Cleaned to a high standard.
Inspection areas — cleanliness	Good	Cleaned to a good standard.
Inspection areas — cleanliness	Fair	Cleaned to a fair standard.
Inspection areas — cleanliness	Poor	Light cleaning required.
Inspection areas — cleanliness	Unacceptable	Professional cleaning required.
Items — condition	Excellent	Unused or new condition.
Items — condition	Good	May have minor signs of wear, but no obvious faults in appearance or functionality.
Items — condition	Fair	Signs of wear or minor damage present.
Items — condition	Poor	Extensive wear, such as stains, marks, rips or chips.
Items — condition	Unacceptable	Not fit for purpose in present state, such as badly damaged or faulty.
Items — cleanliness	Excellent	Cleaned to a high standard.
Items — cleanliness	Good	Cleaned to a good standard.
Items — cleanliness	Fair	Cleaned to a fair standard; see issues and photographs.
Items — cleanliness	Poor	Light cleaning required; see issues and photographs.
Items — cleanliness	Unacceptable	Professional cleaning required; see issues and photographs.

Inspection area	Condition	Cleanliness	Defects	Photos
Bedroom	Poor	Poor	8	35
Bathroom	Unacceptable	Poor	7	24

General detector details	Tested?	General detector comments
Not specified	Yes	No comments recorded

Area	Date	Condition	Cleanliness	Description and recorded defects
Bedroom	5 January 2026	Poor	Poor	Door, ceiling, window, blinds, wardrobe and television as per inventory; ceiling included a watermark. Lighting worked as expected. Walls were scuffed and scratched at inventory; stain marks were new. Flooring had previously recorded burn damage and multiple stains requiring professional cleaning. Mattress staining not noted on inventory. Table missing. Defects: stained radiator cover; stained/scuffed walls; carpet burn damage; carpet stains; evidence of water ingress to ceiling; stained mattress; dirty boxing; missing table and chair.
Bathroom	5 January 2026	Unacceptable	Poor	Door, ceiling and lighting as per inventory. Plastic-clad walls and other walls in fair condition. Bath required limescale and dirt cleaning; shower, bathing equipment and basin tap required limescale cleaning. Bath tap dripping. Boxing required repainting or repair due to water egress from shower area. Shelving unit burnt or stained. Toilet in fair condition; basin damaged and plug broken. Some waste items dumped. Light cleaning required due to limescale. Water damage present on boxing and flooring; flooring stained. Defects: limescale cleaning; water damage; stained flooring; broken plug; dumped items; shelf defects; dripping bath tap.

Observations

- The bedroom received Poor ratings for both condition and cleanliness.
- The bathroom received an Unacceptable condition rating and a Poor cleanliness rating.
- The report states that lighting worked as expected in the bedroom.
- The bedroom ceiling had a watermark, and the report records evidence of water ingress to the ceiling.
- The bedroom carpet had previously recorded burn damage and had multiple stains requiring professional cleaning.
- The bedroom mattress was stained; this was not noted on the inventory.
- The bedroom table was missing; the defect summary records a missing table and chair.
- The bathroom had limescale and dirt requiring cleaning, water damage to boxing and flooring, stained flooring, a broken plug, dumped waste items, shelf defects and a dripping bath tap.
- The bathroom shelving unit was described as burnt or stained, and the boxing required repainting or repair due to water egress from the shower area.
- Detectors were marked as tested Yes; no detector comments were entered.

Findings

- The bedroom had multiple recorded defects, including new wall stain marks, carpet staining, a mattress stain not listed in the inventory, a stained radiator cover, dirty boxing, and missing furniture.
- The bathroom had cleaning needs and condition defects, including limescale, water damage, damaged basin/plug, shelf defects and a dripping bath tap.
- The report contains photographs for both inspected areas. The summary records 35 bedroom photographs and 24 bathroom photographs.

Conclusions

- The report records a Poor condition and cleanliness rating for the bedroom and an Unacceptable condition and Poor cleanliness rating for the bathroom.
- The report is an assessment of observed condition and cleanliness; it does not provide repair recommendations or costs.

Image evidence

Neutral image placeholder

Bedroom photo 1 of 35: General bedroom view showing carpet, wall and room perimeter.

Neutral image placeholder

Bedroom photo 2 of 35: General view showing the bedroom ceiling and lighting.

Neutral image placeholder

Bedroom photo 3 of 35: General view toward the doorway and carpet.

Neutral image placeholder

Bedroom photo 4 of 35: General bedroom view showing walls and carpet.

Neutral image placeholder

Bedroom photo 5 of 35: General view of ceiling and room interior.

Neutral image placeholder

Bedroom photo 6 of 35: General view of the bed and bedroom furnishings.

Neutral image placeholder

Bedroom photo 7 of 35: General view of the room and carpet.

Neutral image placeholder

Bedroom photo 8 of 35: General view of the room, furnishings and window.

Neutral image placeholder

Bedroom photo 9 of 35: General view of the doorway and carpet.

Neutral image placeholder

Bedroom photo 10 of 35: General view of the window area and furnishings.

Neutral image placeholder

Bedroom photo 11 of 35: General view of carpet and room perimeter.

Neutral image placeholder

Bedroom photo 12 of 35: General view of the bedroom interior.

Neutral image placeholder

Bedroom photo 13 of 35: Staining on the radiator cover.

Neutral image placeholder

Bedroom photo 14 of 35: Staining on the radiator cover.

Neutral image placeholder

Bedroom photo 15 of 35: Stained and scuffed wall surface.

Neutral image placeholder

Bedroom photo 16 of 35: Stained and scuffed wall surface.

Neutral image placeholder

Bedroom photo 17 of 35: Stained and scuffed wall surface.

Neutral image placeholder

Bedroom photo 18 of 35: Stained and scuffed wall surface.

Neutral image placeholder

Bedroom photo 19 of 35: Stained and scuffed wall surface.

Neutral image placeholder

Bedroom photo 20 of 35: Stained and scuffed wall surface.

Neutral image placeholder

Bedroom photo 21 of 35: Burn damage to the carpet.

Neutral image placeholder

Bedroom photo 22 of 35: Staining on the carpet.

Neutral image placeholder

Bedroom photo 23 of 35: Staining on the carpet.

Neutral image placeholder

Bedroom photo 24 of 35: Staining on the carpet.

Neutral image placeholder

Bedroom photo 25 of 35: Staining on the carpet.

Neutral image placeholder

Bedroom photo 26 of 35: Staining on the carpet.

Neutral image placeholder

Bedroom photo 27 of 35: Staining on the carpet.

Neutral image placeholder

Bedroom photo 28 of 35: Staining on the carpet.

Neutral image placeholder

Bedroom photo 29 of 35: Staining on the carpet.

Neutral image placeholder

Bedroom photo 30 of 35: Evidence of water ingress to the ceiling.

Neutral image placeholder

Bedroom photo 31 of 35: Staining on the mattress.

Neutral image placeholder

Bedroom photo 32 of 35: Staining on the mattress.

Neutral image placeholder

Bedroom photo 33 of 35: Staining on the mattress.

Neutral image placeholder

Bedroom photo 34 of 35: Dirt on the boxing.

Neutral image placeholder

Bedroom photo 35 of 35: Dirt on the boxing.

Neutral image placeholder

Bathroom photo 1 of 24: General bathroom view showing the bath, basin and shower area.

Neutral image placeholder

Bathroom photo 2 of 24: General bathroom view showing the fixtures and flooring.

Neutral image placeholder

Bathroom photo 3 of 24: General view of the bathroom ceiling and light.

Neutral image placeholder

Bathroom photo 4 of 24: General view of the basin and bathroom fittings.

Neutral image placeholder

Bathroom photo 5 of 24: General view of the bathroom interior.

Neutral image placeholder

Bathroom photo 6 of 24: Limescale requiring light cleaning on bathroom fittings.

Neutral image placeholder

Bathroom photo 7 of 24: Limescale requiring light cleaning on bathroom fittings.

Neutral image placeholder

Bathroom photo 8 of 24: Limescale requiring light cleaning on bathroom fittings.

Neutral image placeholder

Bathroom photo 9 of 24: Limescale requiring light cleaning on bathroom fittings.

Neutral image placeholder

Bathroom photo 10 of 24: Water damage present on boxing and flooring.

Neutral image placeholder

Bathroom photo 11 of 24: Water damage present on boxing and flooring.

Neutral image placeholder

Bathroom photo 12 of 24: Water damage present on boxing and flooring.

Neutral image placeholder

Bathroom photo 13 of 24: Water damage present on boxing and flooring.

Neutral image placeholder

Bathroom photo 14 of 24: Water damage present on boxing and flooring.

Neutral image placeholder

Bathroom photo 15 of 24: Staining on the bathroom flooring.

Neutral image placeholder

Bathroom photo 16 of 24: Staining on the bathroom flooring.

Neutral image placeholder

Bathroom photo 17 of 24: Broken basin plug.

Neutral image placeholder

Bathroom photo 18 of 24: Dumped items in the bathroom.

Neutral image placeholder

Bathroom photo 19 of 24: Dumped items in the bathroom.

Neutral image placeholder

Bathroom photo 20 of 24: Dumped items in the bathroom.

Neutral image placeholder

Bathroom photo 21 of 24: Defect to the bathroom shelf.

Neutral image placeholder

Bathroom photo 22 of 24: Defect to the bathroom shelf.

Neutral image placeholder

Bathroom photo 23 of 24: Defect to the bathroom shelf.

Neutral image placeholder

Bathroom photo 24 of 24: Dripping bath tap.