Northbridge Lettings

Check-out inspection report

Records the condition, cleanliness, meter information, defects and photographic evidence for the check-out inspection of Flat 10, 160 Alder Lane, Westmarsh, ZZ8 9ZZ.

Appointment date: 25 February 2025. Assessor: Northbridge Lettings.

The report provides a visual, room-by-room schedule of condition and contents. Where the assessor makes no comment about an element or item, it is treated as being in good, clean, serviceable condition and without defects. Observed defects and poor condition are described and supported by photographs.

The report is not a structural survey or repair-cost assessment. Fixtures and fittings are listed but may not have been tested. Inaccessible and loft areas are not inspected; locked rooms and outbuildings containing landlord belongings are not inspected. The report remains the property of the instructing party and is not to be used without written permission.

End-of-tenancy guidance: the property and its contents are expected to be left in a similar condition and state of cleanliness to the pre-tenancy report, allowing for fair wear and tear. Repair, replacement or professional cleaning costs may be deducted from the tenant's deposit; receipts should be retained where work is carried out. Cleaning should be thorough and the property left tidy. Carpets and curtains should be professionally cleaned where required by the inventory or tenancy agreement; vinyl or tile flooring should be clean and free of cracks or tears. Decor should be left in the same state as at the start of the tenancy; hooks, nails, screws and holes may need to be removed or repaired, and excessive marks and fingerprints removed. Refrigerators and freezers should be defrosted, switched off and left open. Ovens, hobs, extractor units and microwaves should be cleaned, including burnt-on deposits, grease, doors and seals. Applicable gardens should be left neat and tidy. Smoke and carbon monoxide alarms were stated to have been checked and working as of the report date; tenants are responsible for keeping them in working order and reporting faults other than battery replacement.

The report's condition ratings range from Excellent (unused or new) through Good, Fair and Poor to Unacceptable (not fit for purpose in its present state). Cleanliness ratings range from Excellent (cleaned to a high standard) through Good and Fair to Poor (light cleaning required) and Unacceptable (professional cleaning required).

Area	Condition	Cleanliness	Defects	Photos
Entrance/Hallway	Fair	Poor	2	10
Bedroom 1	Poor	Unacceptable	3	15
Bedroom 1 en-suite	Fair	Poor	3	13
Living Room	Poor	Fair	2	12
Kitchen	Poor	Unacceptable	5	20
Bathroom	Poor	Unacceptable	4	23
Bedroom 2	Unacceptable	Unacceptable	2	17

Energy type	Date	Reading or note	Location	Serial number	Meter type
Electricity	25 February 2025	Need To Be Requested From Buildings Management			

Energy type	Date	Reading or note	Location	Serial number	Meter type
Water	25 February 2025	1220			

Category	Area	Recorded defects
General	Bedroom 1	Chest of drawers missing
Cleaning	Entrance/Hallway	Requires light clean
Cleaning	Bedroom 1	Carpet not vacuumed
Cleaning	Bedroom 1 en-suite	General clean required
Cleaning	Living Room	Dusty flooring
Cleaning	Kitchen	Dirty sink; dirty hob; dirty floor; freezer requires defrost
Cleaning	Bathroom	Dirty sink; dirty bath and shower; dirty flooring; dirty toilet
Cleaning	Bedroom 2	Carpet requires clean
Maintenance	Entrance/Hallway	Damaged overhead closer requires repair
Maintenance	Bedroom 1	Balcony doors stuck
Maintenance	Bedroom 1 en-suite	Extractor fan does not activate; peeling paint
Maintenance	Living Room	Coffee stain on walls
Maintenance	Kitchen	Cupboards peeling
Maintenance	Bedroom 2	Damage to walls

Observations

- No external areas were applicable.
- The water meter reading was 1220 on 25 February 2025. An electricity reading was not available in the report; it says it needs to be requested from building management.
- The detector section records Tested? No. No detector comments are provided.
- The inspection records cleaning issues in the entrance/hallway, bedroom 1, bedroom 1 en-suite, living room, kitchen, bathroom and bedroom 2, and maintenance or condition defects in several of those areas.
- The assessor declaration states that the report reflects the assessor's assessment. The signature was received on 2 November 2024 at 10:44:14.

Findings

- Entrance/Hallway — Condition Fair; cleanliness Poor. Front door, ceiling, lighting, walls and cupboard were recorded as per inventory. Cleaning was required; the summary notes a light clean. The overhead door closer was damaged and requires repair.
- Bedroom 1 — Condition Poor; cleanliness Unacceptable. Door, ceiling and lighting were recorded as per inventory with no issues. Walls had very minor marks considered consistent with fair wear and tear. Balcony was recorded as per inventory with no issues; blinds and radiator were recorded as per inventory. Flooring/carpet was dirty and required vacuum cleaning. Chest of drawers was missing. Wardrobe was recorded as per inventory with no issues. Balcony doors did not open and were recorded as stuck.

- Bedroom 1 en-suite — Condition Fair; cleanliness Poor. Door, ceiling, radiator, flooring and toilet were recorded as per inventory with no issues, except the walls showed a peeling area. Basin and shower required cleaning. The extractor fan was non-functional and did not activate.
- Living Room — Condition Poor; cleanliness Fair. Laminate flooring was dusty and required cleaning. Door, ceiling, balcony, balcony windows and radiator were recorded as per inventory with no issues, except blinds had bent slats not mentioned in the inventory. A coffee stain was recorded on the walls.
- Kitchen — Condition Poor; cleanliness Unacceptable. Walls and tiled splashback were recorded as per inventory. Cupboard fronts and internal cabinets were clean; the oven was clean. The hob and metal splashback were very dirty, worktops were dirty, and the sink and taps were filthy and required professional cleaning. Washing machine and fridge were in fair condition. Freezer required defrosting and cleaning. Melamine kitchen cabinets were peeling.
- Bathroom — Condition Poor; cleanliness Unacceptable. Door, ceiling and lighting were recorded as per inventory. Flooring, sink, bath, shower enclosure and equipment, toilet, dark grey painted walls and mirror were dirty and required professional cleaning. Wallpaper walls were in poor condition. The area above the toilet was in very poor condition and required renewal.
- Bedroom 2 — Condition Unacceptable; cleanliness Unacceptable. Door, ceiling, lighting, window and blinds were recorded as per inventory with no issues. White-painted walls had gouges not mentioned in the inventory. Radiator issues were noted. Flooring was in very poor condition and required professional cleaning; the carpet required cleaning.

Conclusions

- The report records a broad requirement for cleaning, with Unacceptable cleanliness ratings in bedroom 1, the kitchen, bathroom and bedroom 2.
- Reported maintenance or condition matters include a damaged hallway overhead closer, stuck balcony doors in bedroom 1, a non-functioning en-suite extractor fan, peeling en-suite paint, a coffee stain on living-room walls, peeling kitchen cupboards, gouged bedroom 2 walls and radiator issues in bedroom 2.
- The report is an inspection record and does not state that any cleaning or repairs were subsequently completed.

Image evidence

Neutral image placeholder

Water meter photograph: shows the water meter; the recorded reading is 1220.

Neutral image placeholder

Detector photograph: shows a ceiling-mounted detector. The report records that detectors were not tested.

Neutral image placeholder

Entrance/Hallway, 9 general overview photographs: show the entrance, hallway, doors, flooring and adjoining areas. One additional photograph is specifically captioned as showing the damaged overhead closer requiring repair.

Neutral image placeholder

Bedroom 1, 15 photographs: general views show the room, flooring, wardrobe and balcony doors. The room record notes dirty carpet, missing chest of drawers and balcony doors that do not open.

Neutral image placeholder

Bedroom 1 en-suite, 13 photographs: general views show the toilet, basin, shower enclosure and room surfaces. Defect photographs show the inactive extractor fan and peeling paint.

Neutral image placeholder

Living Room, 12 photographs: general views show the room, windows, blinds and laminate flooring. Defect photographs show the coffee stain on the wall and dusty flooring.

Neutral image placeholder

Kitchen, 20 photographs: general views show the kitchen, cupboards, worktops, appliances, sink and floor. Defect photographs show the dirty sink, dirty hob, dirty floor, freezer requiring defrosting and peeling cupboards.

Neutral image placeholder

Bathroom, 23 photographs: general views show the bathroom fixtures and tiled flooring. Defect photographs show the dirty sink, dirty bath and shower, dirty flooring and dirty toilet.

Neutral image placeholder

Bedroom 2, 17 photographs: general views show the bedroom, window, walls and carpet. Defect photographs show wall damage and carpet requiring cleaning.