

Routine Inspection Report

Address 1 - 2/191 Enmore Rd, Enmore 2042

Owner Name

Tenant Name

Lease Start / /

Expiry

Lease Details

Rented for

Inspection Date 15 Nov 2025

I write to advise that a visual Routine Inspection Report was conducted at your property.

Please refer to this inspection for any important notes, photos or maintenance issues. Please reply with your instructions on any maintenance issues raised in the report.

If you have any questions in relation to the Routine Inspection Report, please do not hesitate to contact me on Sophia@livinghigh.com.au.

View your photos/videos online via [Gallery Link](#)

Regards

Sophia Russell

Address of Premises:

1 - 2/191 Enmore Rd, Enmore 2042

Detailed Observations From This Inspection

Area of Property	Clean	Undamaged	Working	Maintenance	Notes
Bedroom 1					

Disclaimer:

This Routine Inspection Report is a visual inspection only and is carried out by this agency to assess the manner in which the tenants are maintaining your property and identify any maintenance required.

As your property manager our role is to manage the tenancy. We are not qualified to assess the structural aspects of areas, including but not limited to, staircases, decking and balconies, or to ensure that plumbing, electrical or gas fixtures or fittings, glass windows, doors and balustrades, smoke alarms, pests (ie. termites), asbestos, swimming pool safety barriers (and associated fittings) comply and operate in accordance with applicable building/council codes and/or laws and regulations.

This agency recommends that all landlords have regular inspections carried out by suitably qualified licensed and insured contractors and experts in the appropriate area when necessary.

Media

[Bedroom 1:](#)

Photo: Taken: 15/11/2025 - 13:28



[Bedroom 1:](#)

Photo: Taken: 15/11/2025 - 13:28




[Bedroom 1:](#)

Photo: Taken: 15/11/2025 - 13:28




[Bedroom 1:](#)

Photo: Taken: 15/11/2025 - 13:28



[Bedroom 1:](#)

Photo: Taken: 15/11/2025 - 13:28



[Bedroom 1:](#)

Photo: Taken: 15/11/2025 - 13:28



Address of Premises:

1 - 2/191 Enmore Rd, Enmore 2042

[Bedroom 1:](#)

Photo: Taken: 15/11/2025 - 13:28



[Bedroom 1:](#)

Photo: Taken: 15/11/2025 - 13:28




[Bedroom 1:](#)

Photo: Taken: 15/11/2025 - 13:28




[Bedroom 1:](#)

Photo: Taken: 15/11/2025 - 13:28



[Bedroom 1:](#)

Photo: Taken: 15/11/2025 - 13:28



[Bedroom 1:](#)

Photo: Taken: 15/11/2025 - 13:28



Address of Premises:

1 - 2/191 Enmore Rd, Enmore 2042

[Bedroom 1:](#)

Photo: Taken: 15/11/2025 - 13:28



[Bedroom 1:](#)

Photo: Taken: 15/11/2025 - 13:28



[Bedroom 1:](#)

Photo: Taken: 15/11/2025 - 13:28



[Bedroom 1:](#)

Photo: Taken: 15/11/2025 - 13:28



[Bedroom 1:](#)

Photo: Taken: 15/11/2025 - 13:28



[Bedroom 1:](#)

Photo: Taken: 15/11/2025 - 13:28



Address of Premises:

1 - 2/191 Enmore Rd, Enmore 2042

[Bedroom 1:](#)

Photo: Taken: 15/11/2025 - 13:29



[Bedroom 1:](#)

Photo: Taken: 15/11/2025 - 13:29



[Bedroom 1:](#)

Photo: Taken: 15/11/2025 - 13:29



[Bedroom 1:](#)

Photo: Taken: 15/11/2025 - 13:29




[Bedroom 1:](#)

Photo: Taken: 15/11/2025 - 13:29



[Bedroom 1:](#)

Photo: Taken: 15/11/2025 - 13:29



Address of Premises:

1 - 2/191 Enmore Rd, Enmore 2042


[Bedroom 1:](#)

Photo: Taken: 15/11/2025 - 13:29




[Bedroom 1:](#)

Photo: Taken: 15/11/2025 - 13:29




[Bedroom 1:](#)

Photo: Taken: 15/11/2025 - 13:29



[Bedroom 1:](#)

Photo: Taken: 15/11/2025 - 13:29




[Bedroom 1:](#)

Photo: Taken: 15/11/2025 - 13:29



[Bedroom 1:](#)

Photo: Taken: 15/11/2025 - 13:29



Address of Premises:

1 - 2/191 Enmore Rd, Enmore 2042

[Bedroom 1:](#)

Photo: Taken: 15/11/2025 - 13:29

