

STAR ADA Compliance Audit Report

Generated 2026-04-17 05:27:00 UTC

This report summarizes the ADA geometric compliance measurements taken during the most recent STAR scan. Each row is a single measurement event recorded by the compliance engine from the on-chassis BNO055 IMU and the RPLiDAR C1, with cross-validation enforced at plus/minus 0.5 degrees.

Summary

Measurements captured: 5. Violations flagged: 0. Passing: 0.

Measurements are observational. Final legal attestation of ADA compliance remains with the Certified Access Specialist reviewing this report.
github.com/Locked-Inc/STAR - Locked Inc. Capstone Team