# AquaGuard Official Inspection Report

Report ID: INS-30 | Date: 2026-08-20 11:38:00
Inspector: Meera (senior water analyst)
Client Name: Devika S
Water Source: Tap Water (Type: Both Online & Field Inspection)

## 1. AquaGuard AI Diagnostic & Laboratory Values

AI Status prediction: UNSAFE

| | |
|---|---|
| Temperature: 1.0 °C | Dissolved Oxygen: 2.0 mg/L |
| pH Level: 6.0 | BOD: 5.0 mg/L |
| Conductivity: 6.0 uS/cm | Nitrate: 7.0 mg/L |
| Faecal Coliform: 0.0 MPN/100ml | Total Coliform: 0.0 MPN/100ml |

## 2. Online Inspection Recommendations

**Final Recommendation: Safe After Treatment** **Purification Method: UV Purification**

**Recommended Method Details / Remarks:**

Method details for UV Purification: - Description: Ultraviolet radiation treatment to disinfect water. - Used for: Neutralizing pathogens, bacteria, viruses, and cysts. - Water Quality Impact: Disinfects without chemicals, altering DNA of microbes to render them harmless. - Instructions: Flow-through UV chamber unit connected to the main water supply line. - Precautions: Requires clear water (suspended particles block UV rays); does not remove dissolved chemicals. - Maintenance: Clean the quartz sleeve periodically; replace the UV lamp annually.

**Precautions:**

gh

**Follow-up Required: Yes** **Follow-up Date: 2026-08-26**

## 3. Physical Field Observations

| | | |
|---|---|---|
| Water Appearance: Muddy | Water Colour: Brown | Water Odour: Strong |
| Visible Contamination: Yes | Nearby Pollution: No | Drainage/Leakage: Yes |
| Sample Collected: Yes | Sample ID: 1234 | Lab Sent: Yes |

**Field Assessment Summary:**

hjbn

**Recommended Action:**

mhm