AquaGuard Official Inspection Report

Report ID: INS-45 | Date: 2026-09-04 10:22:17
Inspector: Calix (Environmental Water Inspector)
Client Name: Devika S
Water Source: Lake Water (Type: Field Inspection)

3. Physical Field Observations

Water Appearance: Clear	Water Colour: Normal	Water Odour: Mild
Visible Contamination: Yes	Nearby Pollution: Yes	Drainage/Leakage: Yes
Sample Collected: Yes	Sample ID: 7	Lab Sent: Yes

Field Assessment Summary:

n

Recommended Action:

h