AquaGuard Official Inspection Report

Report ID: INS-47 | Date: 2026-09-04 14:10:58
Inspector: Calix (Environmental Water Inspector)
Client Name: Devika S
Water Source: Lake Water (Type: Field Inspection)

3. Physical Field Observations

Water Appearance: Clear	Water Colour: Brown	Water Odour: None
Visible Contamination: Yes	Nearby Pollution: Yes	Drainage/Leakage: Yes
Sample Collected: Yes	Sample ID: 65	Lab Sent: Yes

Field Assessment Summary:

j

Recommended Action:

kj