AquaGuard Official Inspection Report

Report ID: INS-55 | Date: 2026-09-07 14:50:11
Inspector: jay (senior water analyst)
Client Name: Devika S
Water Source: Tap Water (Type: Field Inspection)

3. Physical Field Observations

Water Appearance: Clear
Water Colour: Normal
Water Odour: Mild
Visible Contamination: Yes
Nearby Pollution: Yes
Drainage/Leakage: Yes
Sample Collected: No

Field Assessment Summary:

nm

Recommended Action:

dne