



Water Well And Pump Record



Completion is required under authority of Part 127 Act 368 PA 1978.

Failure to comply is a misdemeanor.

Import ID: 01257504001

Tax No:	Permit No:	County: Alcona		Township: Curtis	
Well ID: 010000000004 Elevation: 842 ft. Latitude: 44.5847801 Longitude: -83.8288204 Method of Collection: GPS Differential (DGPS)		Town/Range: 25N 05E	Section: 4	Well Status: Inactive	WSSN: 2016601
		Source ID/Well No: 001			
		Distance and Direction from Road Intersection: 2016601; NO LOG			
		Well Owner: ALCONA PARK 6W			
Well Address: MI		Owner Address: 2550 S AUSABLE RD GLENNIE, MI			

Drilling Method: Unknown Well Depth: 0.00 ft. Well Type: Replacement Casing Type: Unknown Casing Joint: Unknown Casing Fitting: None Diameter: Borehole:	Well Use: Type II public Date Completed: Height: 0.00 ft. below grade	Pump Installed: No Pressure Tank Installed: No Pressure Relief Valve Installed: No		
Static Water Level: 999.99 ft. Below Grade Well Yield Test:		Yield Test Method: Unknown		
Screen Installed: No Intake: Unknown		Formation Description	Thickness	Depth to Bottom
		No Lithology Information	0.00	0.00
Well Grouted: Yes Grouting Material: Unknown Grouting Method: Unknown Bags: 0.00 Additives: None Depth: 0.00 ft. to 0.00 ft.		Geology Remarks:		
Wellhead Completion: Unknown, 12+ inches above grade		Drilling Machine Operator Name:		
Nearest Source of Possible Contamination: Type: None Distance: Direction:		Employment: Unknown		
Abandoned Well Plugged: No Reason Not Plugged:		Contractor Type: Unknown Reg No:		
		Business Name:		
		Business Address:		
		Water Well Contractor's Certification This well was drilled under my supervision and this report is true to the best of my knowledge and belief.		
		Signature of Registered Contractor		
		Date		
General Remarks:				
Other Remarks:				