



Water Well And Pump Record

Completion is required under authority of Part 127 Act 368 PA 1978.



Import ID: 01257509001

Failure to comply is a misdemeanor.

Tax No:	Permit No:	County: Alcona		Township: Curtis	
Well ID: 010000000005 Elevation: 845 ft. Latitude: 44.5813065 Longitude: -83.8298087 Method of Collection: GPS Differential (DGPS)		Town/Range: 25N 05E	Section: 9	Well Status: Active	WSSN: 2016401
		Source ID/Well No: 001			
		Distance and Direction from Road Intersection: 2016401;001			
		Well Owner: ALCONA COUNTY PARK			
		Well Address: MI		Owner Address: 2550 S AUSABLE RD GLENNIE, MI	

Drilling Method: Hollow Rod Well Depth: 31.00 ft. Well Type: Replacement Casing Type: Steel - black Casing Joint: Unknown Casing Fitting: Drive shoe Diameter: 2.00 in. to 29.00 ft. depth Borehole: 2.00 in. to 31.00 ft. depth	Well Use: Type II public Date Completed: 7/1/1992 Height: 0.00 ft. below grade	Pump Installed: Yes Pump Installation Date: Manufacturer: Baker Monitor Model Number: HD Drop Pipe Length: 0.00 ft. Drop Pipe Diameter: Draw Down Seal Used: No Pressure Tank Installed: No Pressure Relief Valve Installed: No	Pump Installation Only: No HP: Pump Type: Hand Pump Capacity: 5 GPM Pump Voltage: Drilling Record ID:
---	---	--	--

Static Water Level: 12.00 ft. Below Grade Well Yield Test: Pumping level 12.00 ft. after 2.00 hrs. at 10 GPM Yield Test Method: Unknown	<table border="1"> <thead> <tr> <th>Formation Description</th> <th>Thickness</th> <th>Depth to Bottom</th> </tr> </thead> <tbody> <tr> <td>Sand & Gravel</td> <td>8.00</td> <td>8.00</td> </tr> <tr> <td>Lithology Unknown</td> <td>12.00</td> <td>20.00</td> </tr> <tr> <td>Sand & Gravel</td> <td>11.00</td> <td>31.00</td> </tr> <tr><td> </td><td> </td><td> </td></tr> <tr><td> </td><td> </td><td> </td></tr> <tr><td> </td><td> </td><td> </td></tr> <tr><td> </td><td> </td><td> </td></tr> <tr><td> </td><td> </td><td> </td></tr> <tr><td> </td><td> </td><td> </td></tr> <tr><td> </td><td> </td><td> </td></tr> <tr><td> </td><td> </td><td> </td></tr> <tr><td> </td><td> </td><td> </td></tr> <tr><td> </td><td> </td><td> </td></tr> <tr><td> </td><td> </td><td> </td></tr> </tbody> </table>	Formation Description	Thickness	Depth to Bottom	Sand & Gravel	8.00	8.00	Lithology Unknown	12.00	20.00	Sand & Gravel	11.00	31.00																																	
Formation Description	Thickness	Depth to Bottom																																												
Sand & Gravel	8.00	8.00																																												
Lithology Unknown	12.00	20.00																																												
Sand & Gravel	11.00	31.00																																												

Screen Installed: Yes Screen Diameter: 1.25 in. Screen Material Type: Screen Installation Type: Unknown Slot Length Set Between: 7.00 2.00 ft. 29.00 ft. and 31.00 ft. Fittings: Bremer check valve	Filter Packed: No Blank: 0.00 ft. Above	Well Grouted: Yes Grouting Method: Unknown Grouting Material: Bentonite slurry Bags: 0.00 Additives: None Depth: 0.00 ft. to 31.00 ft.	Geology Remarks:
---	--	---	-------------------------

Wellhead Completion: Other, 12+ inches above grade	Drilling Machine Operator Name: DAVID NELSON GRAVES Employment: Unknown
Nearest Source of Possible Contamination: Type: Other Distance: 350 ft. Direction: North	

Abandoned Well Plugged: No Reason Not Plugged:	Contractor Type: Unknown Business Name: Business Address:
---	--

	Water Well Contractor's Certification This well was drilled under my supervision and this report is true to the best of my knowledge and belief.
	Signature of Registered Contractor _____ Date _____

General Remarks:
Other Remarks: Contamination Source 1:Type Unknown, Pump Manufacturer:MONITOR