



Water Well And Pump Record



Completion is required under authority of Part 127 Act 368 PA 1978.

Failure to comply is a misdemeanor.

Import ID: 01257510003

Tax No:	Permit No:	County: Alcona		Township: Curtis		
Well ID: 010000000009 Elevation: 832 ft. Latitude: 44.5739656 Longitude: -83.8220141 Method of Collection: GPS Differential (DGPS)		Town/Range: 25N 05E	Section: 10	Well Status: Active	WSSN: 2015801	Source ID/Well No: 001
		Distance and Direction from Road Intersection: 2015801; NO LOG				
		Well Owner: ALCONA PARK 5E				
		Well Address: MI		Owner Address: 2550 S AUSABLE RD GLENNIE, MI		

Drilling Method: Unknown		Pump Installed: No			
Well Depth: ft.	Well Use: Type II public	Pressure Tank Installed: No			
Well Type: Replacement	Date Completed:	Pressure Relief Valve Installed: No			
Casing Type: Unknown	Height: 0.00 ft. below grade				
Casing Joint: Unknown					
Casing Fitting: None					
Diameter:					
Borehole:					
Static Water Level: 999.99 ft. Below Grade		Formation Description	Thickness	Depth to Bottom	
Well Yield Test:		Yield Test Method: Unknown	No Lithology Information	0.00	0.00
Screen Installed: No Intake: Unknown					
Well Grouted: Yes		Geology Remarks:			
Grouting Method: Unknown					
Grouting Material	Bags	Additives	Depth		
Unknown	0.00	None	0.00 ft. to 0.00 ft.		
Wellhead Completion: Unknown, Other, 12+ inches above grade		Drilling Machine Operator Name:			
Nearest Source of Possible Contamination:		Employment: Unknown			
Type	Distance	Direction			
None					
Abandoned Well Plugged: No		Contractor Type: Unknown			
Reason Not Plugged:		Reg No:			
		Business Name:			
		Business Address:			
		Water Well Contractor's Certification			
		This well was drilled under my supervision and this report is true to the best of my knowledge and belief.			
		Signature of Registered Contractor		Date	
General Remarks:					
Other Remarks:					