



Water Well And Pump Record



Completion is required under authority of Part 127 Act 368 PA 1978.

Failure to comply is a misdemeanor.

Import ID: 01257510005

Tax No:	Permit No:	County: Alcona		Township: Curtis		
Well ID: 01000000011 Elevation: 843 ft. Latitude: 44.5764598 Longitude: -83.8273165 Method of Collection: GPS Differential (DGPS)		Town/Range: 25N 05E	Section: 9	Well Status: Active	WSSN: 2016201	Source ID/Well No: 001
		Distance and Direction from Road Intersection: 2016201; NO LOG				
		Well Owner: ALCONA PARK 2W				
		Well Address: MI		Owner Address: 2550 S AUSABLE RD GLENNIE, MI		

Drilling Method: Unknown Well Depth: 1.00 ft. Well Type: Replacement Casing Type: Unknown Casing Joint: Unknown Casing Fitting: None Diameter: Borehole:	Well Use: Type II public Date Completed: Height: 0.00 ft. below grade	Pump Installed: No Pressure Tank Installed: No Pressure Relief Valve Installed: No				
Static Water Level: 999.99 ft. Below Grade Well Yield Test:		Yield Test Method: Unknown		Formation Description	Thickness	Depth to Bottom
				No Lithology Information	1.00	1.00
Well Grouted: Yes Grouting Material: Unknown Bags: 0.00 Additives: None Depth: 0.00 ft. to 0.00 ft.		Grouting Method: Unknown		Geology Remarks:		
Wellhead Completion: Unknown, Other, 12+ inches above grade						
Nearest Source of Possible Contamination: Type: None Distance: Direction:		Drilling Machine Operator Name: Employment: Unknown				
Abandoned Well Plugged: No Reason Not Plugged:		Contractor Type: Unknown Business Name: Business Address:				
		Reg No:				
		Water Well Contractor's Certification This well was drilled under my supervision and this report is true to the best of my knowledge and belief.				
		Signature of Registered Contractor Date				
General Remarks:						
Other Remarks:						