

Water Well And Pump Record

Completion is required under authority of Part 127 Act 368 PA 1978.



Import ID: 01257510006

Failure to comply is a misdemeanor.

Tax No: 01207010000		Permit No:		County: Alcona			Township: Curtis	
Well ID: 010000000012 Elevation: 835 ft. Latitude: 44.5735342 Longitude: -83.8135398 Method of Collection: GPS Differential (DGPS)				Town/Range: 25N 05E	Section: 10	Well Status: Active	WSSN: 2017201	Source ID/Well No: 001
				Distance and Direction from Road Intersection: 2017201; NO LOG				
				Well Owner: ALCONA PARK 2E				
				Well Address: MI			Owner Address: 2550 S AUSABLE RD GLENNIE, MI	

Drilling Method: Unknown Well Depth: ft. Well Type: Replacement	Well Use: Type II public Date Completed:	Pump Installed: No Pressure Tank Installed: No Pressure Relief Valve Installed: No
Casing Type: Unknown Casing Joint: Unknown Casing Fitting: None	Height: 0.00 ft. below grade	
Diameter:		
Borehole:		

Static Water Level: 999.99 ft. Below Grade Well Yield Test: Yield Test Method: Unknown	Formation Description	Thickness	Depth to Bottom
	No Lithology Information	0.00	0.00
Screen Installed: No Intake: Unknown			

Well Grouted: Yes Grouting Method: Unknown				Geology Remarks:
Grouting Material Unknown	Bags 0.00	Additives None	Depth 0.00 ft. to 0.00 ft.	
Wellhead Completion: Unknown. Other. 12+ inches above grade				

Nearest Source of Possible Contamination:			Drilling Machine Operator Name:
Type	Distance	Direction	Employment: Unknown
None			
			Contractor Type: Unknown Reg No:

Abandoned Well Plugged: No	Business Name:
Reason Not Plugged:	Business Address:

	Water Well Contractor's Certification This well was drilled under my supervision and this report is true to the best of my knowledge and belief.
	Signature of Registered Contractor
	Date

General Remarks:
Other Remarks: