

- [Services](#)
- [Storm Damage](#)
- [Insurance Claims](#)
- [Service Area](#)
- [Free Inspection](#)

Local News

Chamblee apartment fire (May 10, 2026) traced to rooftop AC unit — partial roof collapse reported at Windsor Parkview Apartments on Peachtree Blvd.

Roof Safety Alert — Metro Atlanta

A Chamblee Apartment Fire Started on the Roof. Here's What Every Atlanta Homeowner Needs to Inspect Right Now.

By **Peachtree Roofing & Exteriors** 📍 **Serving Metro Atlanta, GA**

Published **May 2026** 🕒 6 min read

On Mother's Day evening, May 10, 2026, residents of the Windsor Parkview Apartments on Peachtree Boulevard in Chamblee were forced from their homes when a fire broke out — one that firefighters traced directly to an air conditioning unit sitting on the roof. Despite crews

containing the blaze, the building suffered a partial roof collapse.

Fortunately, no injuries were reported — but dozens of families lost access to their homes, their belongings, and their sense of security, all because of something on top of the building that most residents never thought about.

"A fire at the Windsor Parkview Apartments in Chamblee started from an air conditioning unit on the roof. Firefighters contained most of the blaze to the roof despite a partial roof collapse."

— *FOX 5 Atlanta, May 10, 2026*

Here at Peachtree Roofing & Exteriors, we've been serving Atlanta-area homeowners across DeKalb, Fulton, Cobb, Gwinnett, and Cherokee counties for years. And when we see a story like this break out of our own backyard — on Peachtree Boulevard, no less — we feel an obligation to speak up. Because what happened at that Chamblee apartment complex is not as uncommon as you might think. It just doesn't always make the evening news.

Why Rooftop HVAC Units Are a Hidden Fire Risk in Atlanta Homes

Central air conditioning is not optional in Georgia — it's survival. But what most homeowners don't realize is that the penetrations, electrical connections, and condensate drainage systems that tie your HVAC unit to your roof are among the most vulnerable points on your entire home. They are exposed to UV rays year-round, soaked by Atlanta's frequent afternoon thunderstorms, and often go uninspected for years at a stretch.

Here's what can go wrong — and frequently does — when rooftop HVAC

systems aren't properly maintained alongside your roof:

- 1

Electrical arcing from aging conduit seals. Condensation, UV degradation, and rodent activity can compromise the electrical conduit running from your AC unit through the roof deck. When insulation fails, arcing can ignite nearby insulation, decking, or attic materials.

- 2

Blocked condensate lines causing water intrusion. When condensate drain lines clog — common with Atlanta's humidity and debris — water backs up and saturates the roof deck around the penetration. Saturated wood rots, creating structural weakness and mold pathways directly into your living space.

- 3

Failed flashing around HVAC curbs and penetrations. Every point where equipment meets your roof requires watertight flashing. In Georgia's climate, this flashing degrades faster than most homeowners expect — typically every 8–12 years — and its failure is invisible from ground level.

- 4

Combustible debris accumulation. Leaves, pine straw, and organic matter collect around rooftop equipment and inside curbed platforms. In dry conditions, this creates tinder that an electrical fault or HVAC malfunction can ignite rapidly.

The Inspection Atlanta Homeowners Are Skipping

Most Atlanta homeowners schedule HVAC service annually — they get

their filters changed, their coils cleaned, their refrigerant checked. What almost no one does is have a roofing professional inspect the roof simultaneously. Your HVAC contractor inspects the unit. Your roofer inspects the roof. Nobody inspects the critical intersection between the two.

That's the gap that Peachtree Roofing & Exteriors specifically addresses. When our certified inspectors come to your home in Buckhead, Decatur, Marietta, Alpharetta, Dunwoody, or anywhere else across metro Atlanta, we don't just look at your shingles. We evaluate every penetration point — HVAC curbs, pipe boots, exhaust vents, skylights — as an integrated system.

Signs your rooftop HVAC penetration needs immediate attention:

- ✓
Water stains on ceiling near air handler or ductwork
- ✓
Soft spots or discoloration on roofing material around AC unit
- ✓
Musty smell in upper floors or attic spaces
- ✓
HVAC unit is 10+ years old and hasn't had a rooftop inspection
- ✓
Visible rust streaking down roofline from equipment

Peachtree Roofing & Exteriors — Metro Atlanta Service Area

Fulton County Atlanta, Buckhead, Sandy Springs, Alpharetta, Roswell

DeKalb County Decatur, Chamblee, Dunwoody, Tucker, Stone Mountain

Cobb County Marietta, Smyrna, Kennesaw, Acworth, Powder Springs

Gwinnett County Lawrenceville, Duluth, Norcross, Suwanee, Buford

Cherokee County Canton, Woodstock, Ball Ground, Holly Springs

Douglas & Paulding Douglasville, Lithia Springs, Dallas, Hiram

What Happened in Chamblee Is a Wake-Up Call — Not Just for Apartment Residents

It would be easy to read the Chamblee story and think, "That was an apartment complex — my house is different." And in some ways, it is. But residential homes across DeKalb County, Fulton County, and the broader Atlanta metro face the exact same risks from aging rooftop penetrations and HVAC interfaces. In fact, standalone homes often face greater risk because there is no building maintenance staff monitoring the roof at regular intervals.

If your home was built between 2000 and 2012 — during Atlanta's last major construction boom — your roof is now between 14 and 26 years old. The flashing around your HVAC, the sealants around your pipe boots, and the waterproofing around every penetration point are aging on the same timeline. You may not have a problem today. But without a professional inspection, you won't know until you do.

Schedule Your Free Roof & Penetration Inspection

Peachtree Roofing & Exteriors offers no-obligation inspections for homeowners across metro Atlanta. We'll evaluate your HVAC penetrations, flashing integrity, and overall roof health — and give you a written report with no pressure.

After Chamblee: Three Things to Do This Week

You don't have to wait for a fire to take action. Here are three concrete steps Atlanta homeowners can take right now to reduce their risk:

- 1

Do a visual check from the ground. Use binoculars if needed.

Look at the area immediately surrounding your outdoor AC unit or any rooftop equipment. Look for rust streaking, lifted flashing, displaced shingles, or organic debris accumulation. If anything looks wrong, call a roofer.

- 2

Check your attic. On a bright day, look for light penetrating through the roof deck near any HVAC penetrations. Check for water staining, discoloration, or soft wood. Any of these signal active or past water intrusion at a penetration point.

- 3

Ask your HVAC tech to document the roof condition at their next visit. They're not roofers, but they can photograph anything that looks unusual around the unit. Then share those photos with a licensed roofing contractor for an expert evaluation.

The families at Windsor Parkview Apartments didn't know what was sitting on top of their building. You have the opportunity to know what's on top of yours — and to act before a news crew is filming it.

Peachtree Roofing & Exteriors is locally owned, fully licensed in Georgia, and committed to protecting Atlanta families with the same care we'd give

our own homes. Give us a call, and let's make sure your roof never becomes a headline.

Free Roof Inspection

No obligation. Written report included. Serving all of Metro Atlanta.

(404) 555-0190 [Schedule Online →](#)

Roof Inspection Checklist

HVAC penetration flashing

Pipe boot seals & collars

Shingle granule loss

Ridge cap integrity

Valley flashing condition

Gutter attachment & slope

Attic ventilation & moisture

Deck & structural integrity

We Serve Your Neighborhood

- Buckhead & Midtown Atlanta
- Chamblee & Doraville
- Decatur & Avondale Estates
- Marietta & East Cobb
- Alpharetta & Milton
- Woodstock & Canton
- Lawrenceville & Duluth
- Smyrna & Vinings

Related Posts

→ [What Atlanta's Storm Season Means for Your Roof in 2026](#)

→ [New Georgia Law Lets Homeowners Use Tax-Advantaged Funds for Roof Deductibles](#)

→ [How to Document Roof Damage for an Insurance Claim in Georgia](#)

Peachtree Roofing & Exteriors — Licensed Georgia Roofing Contractor

Proudly serving Fulton, DeKalb, Cobb, Gwinnett, Cherokee, Douglas, and Paulding Counties since [Year].