INSPECTION REPORT

Policy Number: POL100002

Proposer: Satpura Plastics Pvt Ltd

Risk Location: Unit 7, Peenya Industrial Area, Bengaluru

Sum Insured: 390,000,000

Date: 2026-08-01

Property Condition: Good, well maintained

Fire Protection: Hydrants and sprinklers tested

Surveyor: A. Kulkarni

Signature: _____