

Illegal Parking Detection Report

Processed on 2024-05-20 07:28:42




Report Overview

Dataset	output2
Number of Illegally Parked Cars	1 detected
Number of Images	80 processed
Processing Time	4 minutes and 20.80 seconds
Mission Duration	55 seconds




Illegally Parked Cars

Estimated Number of IPCs: 1, Estimated number of noise points: 25



Screenshot	Location	Timestamp	Time Parked	# of Detections
	25.38452601052214,	2024-04-29	39 seconds 5	55 / 80 images
	51.48979564842517	13:11:54		(68.75%)





Mission Details

Distance Travelled	221.89 meters
Relative Altitude Range	24.61 to 25.28 meters above ground
Mission Start Time	2024-04-29 13:11:46
Mission End Time	2024-04-29 13:12:41
Mission Duration	55 seconds

Camera Details

Image Resolution	4000x3000 pixels
Focal Length	4.40 mm
Mega Pixels	12.0 MP
Capture Rate	1 images per second
Field of View	73.7 deg