

	PT. MULTO KONTROL NUSANTARA		Doc No : FM-HSE-10-22
	DAFTAR PERIKSA TOOLS BOX & TOOLS BOARD WAREHOUSE No Reg. : MKN-08, Lokasi : D-8		Publish Date : 19 Sept. 09
			Rev. 01
			Date Review :

No.	Description	Merk/Type	Unit	Qty	Tools Condition			Remarks
					Good	Enough	Broken	
1	Tang potong besar	Proskit	Ba	1	✓			
2	Tang Kombinasi	proskit	Ba	1	✓			
3	Tang lancip	Tekiro	Ba	1	✓			
4	Palu cabut paku	Tekiro	Ba	1	✓			
5	Pisau / Cutter	Tekiro	Ba	2	✓			
6	Kunci inggris "	Tekiro	Ba.	1	✓			
7	Obeng flat kecil	vessel	Ba	2				
8	Obeng plus kecil	vessel	Ba.	2				
9	Obeng flat besar	vessel		1				
10	Obeng plus besar	vessel	Ba.	1	✓			
11	Obeng flat krus	vessel	Ba	1				
12	Obeng plus krus	vessel	Ba.	1				
13	Tone Generator	Goldtools	set	1	✓			
14	Inserting Tool Krone	Krone	Ba	1				
15	Inserting Tool Systimax	Fluke	Ba	1				
16	Crimping disconnect	Sanliq	Ba.	1				
17	Crimping RJ45	Comscope	Ba.	1				
18	Multitester Digital	Sanwa	Ba.	1				
19	LAN Tester	Goldtools		1				Dikembalikan
20	Gergaji besi	Krisbow	Ba.	1				
21	Meteran 5m	Krisbow	Ba.	1				
22	Senter							N/A
23	Kunci tork	Proskit	Ba.	1				
24	Kunci L							N/A
25	Box alat	Tekiro	Ba.	1				
26	Gembok Tools Box		Ba.	1				
27	Crimping RS 63.	Sanliq	Ba.	1				

Catatan : Apabila ada kerusakan atau kehilangan tools, segera buat laporan kerusakan/kehilangan pada form yang sudah ada.

Tanggal, 17 / 10 / 22

Diinspeksi Oleh,

Diketahui Oleh,

Penanggung Jawab Tools (Q 4)

(JUFRI R)
Posisi : Act Supv Telco
ID/BN : Z 50322

()
Posisi :
ID/BN :

Nama : Imam Aulla	TTD
Posisi : Teknisi	
ID : Z 104605	
Nama :	TTD
Posisi :	
ID :	

Imam Aulia


	PT. MULTO KONTROL NUSANTARA		Doc No : FM-HSE-10-22
	DAFTAR PERIKSA TOOLS BOX & TOOLS BOARD WAREHOUSE No Reg. : MKN-08, Lokasi : D-8		Publish Date : 19 Sept. 09
			Rev. 01
			Date Review :

No.	Description	Merk/Type	Unit	Qty	Tools Condition			Remarks
					Good	Enough	Broken	
1	Tang potong besar	proskit	l		✓			
2	Tang Kombinasi	Tekiro	l		✓			
3	Tang lancip	proskit	l		✓			
4	Palu cabut paku	Krisbow	l		✓			
5	Pisau / Cutter	proskit	l		✓			
6	Kunci inggris "	Krisbow	l		✓			
7	Obeng flat kecil	vessel	l		✓			
8	Obeng plus kecil	vessel	l		✓			
9	Obeng flat besar	vessel	l		✓			
10	Obeng plus besar	vessel	l		✓			
11	Obeng flat kurus	vessel	l		✓			
12	Obeng plus kurus	vessel	l		✓			
13	Tone Generator	Goldtools	l		✓			
14	Inserting Tool Krone	Krone	l		✓			
15	Inserting Tool Systimax	Fluke	l		✓			
16	Crimping disconnect	Sanflq	l		✓			
17	Crimping RJ45	Comscope	l		✓			
18	Multitester Digital	Fluke 106	l		✓			
19	LAN Tester	Goldtools	l		✓			N/A
20	Gergaji besi	Krisbow	l		✓			
21	Meteran 5m	Krisbow	l		✓			
22	Senter							N/A
23	Kunci tork	Prosnip						N/A
24	Kunci L							N/A
25	Box alat	Krisbow	l		✓			
26	Gembok Tools Box		l		✓			

Catatan : Apabila ada kerusakan atau kehilangan tools, segera buat laporan kerusakan/kehilangan pada form yang sudah ada.

Tanggal, 14 / 10 / 20

Diinspeksi Oleh,



(JUFRI R)
Posisi : Act Supv Telco
ID/BN : Z 50322

Diketahui Oleh,

()
Posisi :
ID/BN :

Penanggung Jawab Tools (Q 4)

Nama : Indra P	TTD
Posisi : Jr Teknisi	
ID : Z 104603	
Nama :	TTD
Posisi :	
ID :	

Indra Pranata

	PT. MULTO KONTROL NUSANTARA		Doc No : FM-HSE-10-22
	DAFTAR PERIKSA TOOLS BOX & TOOLS BOARD WAREHOUSE No Reg. : MKN-08, Lokasi : D-8		Publish Date : 19 Sept. 09
			Rev. 01
			Date Review :

No.	Description	Merk/Type	Unit	Qty	Tools Condition			Remarks
					Good	Enough	Broken	
1	Tang potong besar	Tekiro		1				
2	Tang Kombinasi	proskit		1				
3	Tang lancip	proskit		1				
4	Palu cabut paku	proskit		-				N/A
5	Pisau / Cutter	proskit		1				
6	Kunci inggris "	Krisbow		1				
7	Obeng flat kecil	vessel		1				
8	Obeng plus kecil	vessel		1				
9	Obeng flat besar	vessel		1				
10	Obeng plus besar	vessel		1				
11	Obeng flat kurus	vessel		1				
12	Obeng plus kurus	vessel		1				
13	Tone Generator	Goldtools		1				
14	Inserting Tool Krone	Krone		1				
15	Inserting Tool Systimax	Fluke		1				
16	Crimping disconnect	Sanliq		1				
17	Crimping RJ45	Sanliq		1				
18	Multitester Digital	Fluke 106		1				
19	LAN Tester	Goldtools		-				N/A
20	Gergaji besi	Krisbow		1				
21	Meteran 5m	Krisbow		1				
22	Senter			-				N/A
23	Kunci tork	Prosnip		1				
24	Kunci L			-				N/A
25	Box alat	Krisbow		1				
26	Gembok Tools Box							


Catatan : Apabila ada kerusakan atau kehilangan tools, segera buat laporan kerusakan/kehilangan pada form yang sudah ada.

Tanggal, 14 / 10 / 2022

Diinspeksi Oleh,

Diketahui Oleh,

Penanggung Jawab Tools (Q 4)


 (JUFRI R)
 Posisi : Act Supv Telco
 ID/BN : Z 50322

()
 Posisi :
 ID/BN :

Nama : Januar P	TTD
Posisi : Jr Teknisi	
ID : Z 101073	
Nama :	TTD
Posisi :	
ID :	

Januar P


	PT. MULTO KONTROL NUSANTARA		Doc No : FM-HSE-10-22
	DAFTAR PERIKSA TOOLS BOX & TOOLS BOARD WAREHOUSE No Reg. : MKN-08, Lokasi : D-8		Publish Date : 19 Sept. 09
			Rev. 01
			Date Review :

No.	Description	Mark/Type	Unit	Qty	Tools Condition			Remarks
					Good	Enough	Broken	
1	Laptop		3	ea	✓			
2	Mata Bor	NACHI	2	set	✓			
3	Test Phone	CHINO	3	ea	✓			
4	Bor DC	BOSCH	3	set	✓			
5	Kunci Pass Ring	TEKIRO	1	set	✓			
6	LAN Tester Golt Tools	FLUKE	1	set	✓			
7	Fluke Network	Fluke	1	ea	✓			
8	Radio Tangan	TAIT	1	ea	✓			
9	Sender Kepala	NITECORE	2	ea	✓			1 ea tdk ada lket kepala
10	Alincheck G2	Net Ally	1	ea	✓			
11	Label Print	Brody	1	ea	✓			MKN 02
12	Fusion Splicer	FITEL	1	ea	✓			MKN 01
13	OTDR	EXFO	1	ea	✓			FTB-200
14	Katrol	PETZL	2	ea	✓			
15	Full Body Harness	KARAM	3	ea	✓			1 ea dibawa ke MKN Banglor.
16	Double Lanyard		3	ea	✓			
17	Pole Harness	INTL	1	ea	✓			SE/M-KNPSCA/SGT/062122
18	Single Lanyard		1	ea	✓			
19	Work Lamp + Battery + Charger Battery	Wimpo	1	set	✓			OE/MKN/Wimpoi/SGI/90722
20	Webbing sling	PETZL	1	ea	✓			WSA - 01
21	Cabiner Sew	PETZL	1	ea	✓			CR - CS
22								

Cat: Form yang sudah ada

Tanggal, 4 / 10 / 2022

Diinspeksi Oleh,



(JUFRI R)

Posisi : Act Supv Telco

ID/BN : Z 50322


Diketahui Oleh,

(_____)

Posisi : _____

ID/BN : _____

Penanggung Jawab Tool's (Q 4)

Nama : Januar	TTD
Posisi : Jr Teknisi	
ID : Z 101073	
Nama :	TTD
Posisi :	
ID :	