



Plant

W067 - Bremen

Yesterday

20.11.25

Area

Bodyshop

All Checks

NOK

Vehicle Type


Multiple selections

Vehicle Side



Links

Vehicle Count Bodyshop 49	Detection Rate 0.064	No Touch Rate Bodyshop 0.00 %	No Touch Rate Left 0.00 %	No Touch Rate Right 0.00 %
C254	S206	V295	W206	X254
No Touch Rate C254 0.00 %	No Touch Rate S206 0.00 %	No Touch Rate V295 0.00 %	No Touch Rate W206 0.00 %	No Touch Rate X254 0.00 %
Vehicle Count IQVIS 15	Vehicle Count IQVIS 3	Vehicle Count IQVIS 0	Vehicle Count IQVIS 1	Vehicle Count IQVIS 30
Vehicle Count MRS 103	Vehicle Count MRS 0	Vehicle Count MRS 0	Vehicle Count MRS 0	Vehicle Count MRS 0

Top 10 Focal Points



Measurements for Point C254 5-6_A1L.GG





Plant

W067 - Bremen

Last 14 Days

07.11.25 - 20.11.25

Vehicle Type

Multiple selections

Prod Number

All

Body Number

95292090

Measurement Point

1-4_A2R.FF

Bodyshop

Assembly

Body Number

-

Measurement Time Z3

-

OK Quote Bodyshop

-

Production Number

-

Measurement Time



-

OK Quote Assembly

-

Details

Measurement Point	Measurement	Min Tolerance	Max Tolerance	Result	Deviation	Body Number	Measurement Point	Measurement	Min Tolerance	Max Tolerance	Result	Deviation	Production Number	Deviation to Bodyshop
-------------------	-------------	---------------	---------------	--------	-----------	-------------	-------------------	-------------	---------------	---------------	--------	-----------	-------------------	-----------------------



W067 - Bremen

W067 - Bremen



Yesterday

Yesterday



20.11.25

Area

Bodyshop



All Checks

NOK



Vehicle Type

Multiple selections



Vehicle Side

Links



Measurement Point

A11



Series	Derivate	Measurement Point	Quantity	Average	Standard deviation	Min	25%	50%	75%	Max
--------	----------	-------------------	----------	---------	--------------------	-----	-----	-----	-----	-----