


ATELIER SEATWORKS
BESPOKE SEAT RESTORATION & REUPHOLSTERY

Before & After


SEAT TRANSFORMATIONS



hello@atelierseatworks.com | +1 (555) 018-2273


The Roadster Bucket

BEFORE



Cracked hide, collapsed foam, split seams

AFTER




Full-grain cognac leather, rebuilt bolsters, gold contrast stitch




The Executive Sport

BEFORE



Sun-faded panels, worn driver bolster

AFTER




Carbon-black nappa, reinforced side bolster, tonal stitch



The Grand Tourer


BEFORE



Torn center panel, brittle vinyl, loose stitching




AFTER



Royal-navy leather, diamond channels, hand-finished piping

The Heritage Coupe


BEFORE



Discolored, flattened cushion, frayed edges



AFTER



Racing-red aniline, re-cored cushion, ivory double stitch