

REPUBLIC OF KENYA

Certificate of Authenticity of Electronic Record

Pursuant to the Evidence Act (Cap 80), Section 106B(4)

Generated by the Oneka AI Infrastructure Auditing Platform

Certificate No: **ONEKA-106B-6CDD1A21-20260308092327**

Date of Issue: **08 March 2026**

SUBJECT PROJECT

Project Name: PROPOSED EXTERNAL PAVING AND REHABILITATION WORKS AT COUNTY ASSEMBLY OF KIRINYAGA OFFICES - KERUGOYA TOWN.

Project UUID: 6cdd1a21-c938-48b4-8cea-4a6acba9b465

Project Type: other

County / Constituency / Ward: Kirinyaga / N/A / N/A

Estimated Value (KES): N/A

ML Risk Level: MEDIUM

Ghost Probability: 0.4250

GPS Coordinates: -0.5000000, 37.2833000 (Source: MANUAL_TEST, Method: MANUAL_PIN)

1. SOURCE OF ELECTRONIC RECORD

Data Source: European Space Agency (ESA) Copernicus Data Space Ecosystem

Repository URL: <https://dataspace.copernicus.eu>

Satellite Sensors: Sentinel-2

The satellite imagery referenced herein was acquired from the European Space Agency (ESA) Copernicus Data Space Ecosystem, a publicly accessible repository of Earth observation data. The raw data is freely available for independent verification at the URL stated above.

2. SCENE ACQUISITION TIMESTAMPS (ISO 8601)

Monitoring Period: 2024-01-01 to 2024-01-01

Total Scenes Analysed: 1

Each satellite scene listed below was captured at the date specified by the sensor's onboard clock, synchronised to UTC via GPS timing systems.

3. PROCESSING ALGORITHM DESCRIPTION & 4. DATA INTEGRITY PROOF

#	Sensor	Scene ID	Acquisition Date	Analysis Type	Processing Date	SHA-256 Hash Source File
1	Sentinel-2	S2B_MSIL2A_20240101T075309_N0510_R135_T37NCF_20240101T103738	2024-01-01	NDVI_change	2026-03-08	N/A meta- unavailable

Algorithm Descriptions:

Scene 1 (Sentinel-2, 2024-01-01): Normalized Difference Vegetation Index (NDVI) computed as (NIR – Red) / (NIR + Red) using Sentinel-2 Band 8 (842 nm) and Band 4 (665 nm). Processing engine: Satpy NDVIProcessor (v1.2). Change detection via temporal linear regression of NDVI mean values over the project monitoring period.

The SHA-256 cryptographic hashes listed above were computed at the time of download from the ESA Copernicus Data Space and stored as immutable metadata in the Oneka S3 object store. Any alteration to the source files after download would produce a different hash value, enabling independent verification of data integrity.

5. CHAIN OF CUSTODY

Processing System: Oneka AI Infrastructure Auditing Platform v1.0.0

Certifying Analyst: Test Analyst

Analyst Title: Principal Investigator

Certificate Generated At: 2026-03-08T09:23:27.036755Z

The satellite data was downloaded from ESA Copernicus Data Space by the Oneka AI Platform, processed using the algorithms described in Section 3, and stored with SHA-256 integrity hashes in a secured AWS S3 bucket with AES-256 server-side encryption. The chain of custody from acquisition to analysis was maintained entirely within the Oneka AI processing environment.

6. SYSTEM OPERATING STATEMENT

The computer system (Oneka AI Infrastructure Auditing Platform) was operating properly at the time the data described herein was produced. The system was functioning within normal parameters and no errors were detected during the processing of the satellite imagery referenced in this certificate.

7. CERTIFICATION & SIGNATURES

I hereby certify that the satellite imagery and analysis results described in this certificate were produced by the Oneka AI Infrastructure Auditing Platform, that the information contained herein is true and correct to the best of my knowledge, and that this certificate satisfies the requirements of Section 106B(4) of the Evidence Act (Cap 80) of the Republic of Kenya.

Name: _____

Title: Certifying Officer, Office of the Auditor
General

Date: _____

Signature: _____

Name: Test Analyst

Title: Principal Investigator

Date: 08 March 2026

Signature: _____