

Exhibit I: Water Treatment Plant Filter No. 2 Reliability Response

Prepared for: Memorandum to the Village Board of Tuxedo Park **Period:** December 2022–January 2023

Administration: Mayor David C. McFadden

Executive finding

DPW returned Filter No. 2 to service after finding a blown control-panel fuse. Coordinated troubleshooting resolved the issue without the quoted \$5,700 Westech site visit.

Chronology

Mayor / admin.	Date or period	Documented event	Result
McFadden	December 14, 2022	Water Treatment Plant filtering process was not operating normally	Village personnel met with VRI representatives, Jeff Voss, and John Bello
McFadden	December 2022	Westech quoted a one-day on-site troubleshooting visit, transportation, and lodging	Quoted cost of \$5,700
McFadden	December 20, 2022–January 17, 2023	DPW found a blown fuse in the control panel and put Filter No. 2 back in service	Second filtration unit restored
McFadden	January 2023	Coordinated calls with Tom Dennis of Westech, Jeff Voss, and Tyler Post resolved the Filter No. 2 issue	\$5,700 site visit avoided
McFadden	Plant configuration	Facility uses a flocculation tank, two updraft dual-media filters, and a clearwell	Confirms Filter No. 2 was one of two filtration units

Precision statement

The records document repair and return to service, not replacement of the entire filter. The risk that failure of the remaining unit could interrupt potable-water production is McFadden's firsthand assessment.

Sources

- Village of Tuxedo Park, [December 2022 Construction Report](#).
- Village of Tuxedo Park, [January 2023 Construction Report](#).
- Village of Tuxedo Park, [DPW Report, December 20, 2022–January 17, 2023](#).
- Orange County, [Regional Ground-Water Study, treatment-facility description](#).