



Repairs Report

Item ID	Item Type	Status	Warranty Date	Damage Type	Repair Date	Date	Cost
10	I1	In Progress	6/20/19 12:00 AM	None	7/18/19 12:00 AM	8/20/19 12:00 AM	20000.0

May 20, 2019

© General Engineering & Business Services (Pte) Ltd