

Estimate ☐	Installation ☐	Charges ☐ Full Contract ☐	
Training ☐	Pre-Install ☐	Warranty ☐ Labour Contract ☐	
Date In: 30-6-26	Date Completed:	SERVICE REPORT NO: 2259	City: Najran Riyadh
Hospital Lana medical	Department: BioMedical Eng. Dept.	P.O. NO. S.C. No.	Tel. Fax.
Equipment Manuf.: Switzerland	Description install	Serial No.: LQ03702	
Requested By:			
Description of the Problem:			
install EMS Dolar Cleft Radial			
Action Taken:			
install EMS Dolar Cleft Radial, Device working.			
Diagnosis Report:			
Spare Parts:			
Required ☐		Replaced ☐	
Code No.	Description	Qty.	Unit Price
		Total	
☐ Working properly &		☐ The above spare parts	Eng. Charges
☐ It is required to be sent to Manufacturer.		☐ Another demonst is required	Grand Total
Remarks:			
Customer Sign	Hospital B.M.E.	Orthoserv Rep.	
		Eng. mohammed ghazwan 30-6-2016	

سجل جاري: 1010251830

Orthopedic Service Est.

مؤسسة خدمة العظم للتجارة

 ص.ب. 286869 الرياض 11323 المملكة العربية السعودية. عضوية رقم 34907 هاتف 014806641 فاكس 012419801
 P.O.Box 286869 Riyadh 11323 Kingdom of Saudi Arabia Membership No 34907 Tel 014806641 Fax: 012419801