




BGAC fill in	 	Non-conforming products report (NCR)	Document no. <u>LG-BGAC-24-001</u>
	Issued by : <u>Nadira A.</u>		Approved by : <u>Sampath</u>
	Department : ☒ Logistic ☐ QM		Date : <u>18-01-24</u> Time : <u>08-20</u>
	Products details		
	Part no. : <u>S11-5401501 (6)</u>		Part name : <u>Sub-Assy Panel INR-LH Side Body</u> RR *
	Vehicle model : <u>EP 12.</u>		Variance : _____
	Lot no. : _____		PO. no. : <u>FA2-2309-07</u>
	Case no. : <u>C1013-20231120-00002</u>		Box no. : <u>B1013-20231120-00006</u>
	SC* : ☐ Safety ☐ Regulation ☐ Function <i>*QM fill in</i>		Q'ty : <u>6</u> EA
	Found place		
	<u>Warehouse</u> ☒ Body ☒ Metal parts ☐ Plastic parts ☐ Assembly ☐ CKD ☐ Local		<u>Production</u> ☐ Body shop ☐ Paint shop ☐ Assembly shop
			<u>Station</u> <u>Unloading Area</u>
	Non-conforming details		
	☐ Wrong Packaging ☒ Packaging damage ☐ Wrong part ☐ Mixed part ☐ Missing part		☐ Rusty ☐ Stains ☐ Dent ☐ Deform ☐ Scratches ☐ Crack ☐ Broken ☐ Malfunction hardware ☐ Part damage from process ☐ Other _____
			<u>Description</u> <u>Part touching</u>
Neta & BGAC fill in	Final judgment ☒ Responsible ☒ Neta ☐ BGAC		Neta judged by (Owner process)  Written name : _____ Date : <u>1-22</u>
			BGAC judged by (Owner process)  Written name : _____ Date : _____
Neta fill in	Neta action		
	☐ Local supplier take action ☐ Request the missing product ☐ Order the damaged product ☐ Replacement ☐ Sorting _____ ☐ Scrap _____ ☐ Other _____ ☐ Rework/Repair → Neta issue rework/repair job order ☒ *Use As Is (UAI) → Neta issue the deviation management In case of "Rework/Repair" & "Use as is" please specify VIN no. : _____ <i>*Safety parts are not allowed</i>		
	Approved by  Written name : _____ Date : <u>1-22</u>		