

VEHICLE CONDITION & DAMAGE REPORT

Inspection form VC-01 | Complete all fields and select one box per group.

1. INSPECTION DETAILS

Report reference
VR-0001

Date (YYYY-MM-DD)
2026-09-04

Time
09:15

Inspection site
Central depot

Inspector name
Sam Taylor

2. VEHICLE IDENTIFICATION

Make
Toyota

Model
Corolla

Model year
2022

Registration
TST 4966

Colour
Blue

Odometer (km)
93,647

Fleet / vehicle reference
FLEET-0101

3. CONDITION CHECKLIST

Overall condition:

☒ Perfect

☐ Damage noted

Component inspected	No damage	Damage
Body panels	☒	☐
Front bumper	☒	☐
Rear bumper	☒	☐
Glass / windows	☒	☐
Mirrors	☒	☐
Lights	☒	☐
Wheels / tyres	☒	☐
Interior	☒	☐

Damage type (select one):

☒ None

☐ Scratch

☐ Dent

☐ Crack

☐ Broken part

☐ Tear

☐ Puncture

☐ Corrosion

Severity:

☒ None

☐ Minor

☐ Moderate

☐ Severe

4. FINDINGS & ACTION

Damage location
None

Damage extent / dimensions
None observed.

Inspection notes / description:

All inspected areas are in perfect condition.

No scratches, dents, cracks or broken parts found.

No damage was recorded during this inspection.

Recommended action:

No repair required.

Driving restriction:

☒ None recorded

☐ Hold for repair

Inspector signature:

Sam Taylor

Page 1 of 1