

VEHICLE CONDITION & DAMAGE REPORT

Inspection form VC-01 | Complete all fields and select one box per group.

1. INSPECTION DETAILS

Report reference

VR-0002

Date (YYYY-MM-DD)

2026-09-05

Time

10:30

Inspection site

West depot

Inspector name

Jamie Reed

2. VEHICLE IDENTIFICATION

Make

Volkswagen

Model

Golf

Model year

2024

Registration

TST 9917

Colour

White

Odometer (km)

46,070

Fleet / vehicle reference

FLEET-0102

3. CONDITION CHECKLIST

Overall condition:

☒ Perfect

☐ Damage noted

Component inspected	No damage	Damage
Body panels	☒	☐
Front bumper	☒	☐
Rear bumper	☒	☐
Glass / windows	☒	☐
Mirrors	☒	☐
Lights	☒	☐
Wheels / tyres	☒	☐
Interior	☒	☐

Damage type (select one):

☒ None

☐ Scratch

☐ Dent

☐ Crack

☐ Broken part

☐ Tear

☐ Puncture

☐ Corrosion

Severity:

☒ None

☐ Minor

☐ Moderate

☐ Severe

4. FINDINGS & ACTION

Damage location

None

Damage extent / dimensions

None observed.

Inspection notes / description:

Vehicle is in perfect condition on inspection.

All panels, glass, lights and fittings are intact.

No damage was recorded during this inspection.

Recommended action:

No repair required.

Driving restriction:

☒ None recorded

☐ Hold for repair

Inspector signature: Jamie Reed