

VEHICLE CONDITION & DAMAGE REPORT

Inspection form VC-01 | Complete all fields and select one box per group.

1. INSPECTION DETAILS

Report reference
VR-0003

Date (YYYY-MM-DD)
2026-09-06

Time
11:45

Inspection site
South depot

Inspector name
Robin Blake

2. VEHICLE IDENTIFICATION

Make
Ford

Model
Focus

Model year
2017

Registration
TST 1243

Colour
Grey

Odometer (km)
97,966

Fleet / vehicle reference
FLEET-0103

3. CONDITION CHECKLIST

Overall condition:

☒ Perfect

☐ Damage noted

Component inspected	No damage	Damage
Body panels	☒	☐
Front bumper	☒	☐
Rear bumper	☒	☐
Glass / windows	☒	☐
Mirrors	☒	☐
Lights	☒	☐
Wheels / tyres	☒	☐
Interior	☒	☐

Damage type (select one):

☒ None

☐ Scratch

☐ Dent

☐ Crack

☐ Broken part

☐ Tear

☐ Puncture

☐ Corrosion

Severity:

☒ None

☐ Minor

☐ Moderate

☐ Severe

4. FINDINGS & ACTION

Damage location
None

Damage extent / dimensions
None observed.

Inspection notes / description:

No damage found on any inspected component.

Vehicle condition is perfect throughout.

No damage was recorded during this inspection.

Recommended action:

No repair required.

Driving restriction:

☒ None recorded

☐ Hold for repair

Inspector signature:

Robin Blake

Page 1 of 1