

VEHICLE CONDITION & DAMAGE REPORT

Inspection form VC-01 | Complete all fields and select one box per group.

1. INSPECTION DETAILS

Report reference <i>VR-0006</i>	Date (YYYY-MM-DD) <i>2026-09-09</i>	Time <i>14:30</i>
Inspection site <i>West depot</i>	Inspector name <i>Sam Taylor</i>	

2. VEHICLE IDENTIFICATION

Make <i>Renault</i>	Model <i>Clio</i>	Model year <i>2018</i>
Registration <i>TST 3420</i>	Colour <i>Green</i>	Odometer (km) <i>46,240</i>
Fleet / vehicle reference <i>FLEET-0106</i>		

3. CONDITION CHECKLIST

Overall condition: ☒ Perfect ☐ Damage noted

Component inspected	No damage	Damage
Body panels	☒	☐
Front bumper	☒	☐
Rear bumper	☒	☐
Glass / windows	☒	☐
Mirrors	☒	☐
Lights	☒	☐
Wheels / tyres	☒	☐
Interior	☒	☐

Damage type (select one):

☒ None	☐ Scratch	☐ Dent	☐ Crack
☐ Broken part	☐ Tear	☐ Puncture	☐ Corrosion

Severity: ☒ None ☐ Minor ☐ Moderate ☐ Severe

4. FINDINGS & ACTION

Damage location <i>None</i>	Damage extent / dimensions <i>None observed.</i>
--------------------------------	---

Inspection notes / description:

All inspected areas are in perfect condition.

No scratches, dents, cracks or broken parts found.

No damage was recorded during this inspection.

Recommended action:

No repair required.

Driving restriction: ☒ None recorded ☐ Hold for repair

Inspector signature: *Sam Taylor*