

# VEHICLE CONDITION & DAMAGE REPORT

Inspection form VC-01 | Complete all fields and select one box per group.

## 1. INSPECTION DETAILS

Report reference  
*VR-0011*

Date (YYYY-MM-DD)  
*2026-09-14*

Time  
*10:45*

Inspection site  
*South depot*

Inspector name  
*Sam Taylor*

## 2. VEHICLE IDENTIFICATION

Make  
*Mazda*

Model  
*3*

Model year  
*2022*

Registration  
*TST4931*

Colour  
*Grey*

Odometer (km)  
*74,236*

Fleet / vehicle reference  
*FLEET-0111*

## 3. CONDITION CHECKLIST

Overall condition:

☒ Perfect

☐ Damage noted

| Component inspected | No damage                           | Damage                   |
|---------------------|-------------------------------------|--------------------------|
| Body panels         | <input checked="" type="checkbox"/> | <input type="checkbox"/> |
| Front bumper        | <input checked="" type="checkbox"/> | <input type="checkbox"/> |
| Rear bumper         | <input checked="" type="checkbox"/> | <input type="checkbox"/> |
| Glass / windows     | <input checked="" type="checkbox"/> | <input type="checkbox"/> |
| Mirrors             | <input checked="" type="checkbox"/> | <input type="checkbox"/> |
| Lights              | <input checked="" type="checkbox"/> | <input type="checkbox"/> |
| Wheels / tyres      | <input checked="" type="checkbox"/> | <input type="checkbox"/> |
| Interior            | <input checked="" type="checkbox"/> | <input type="checkbox"/> |

Damage type (select one):

☒ None

☐ Scratch

☐ Dent

☐ Crack

☐ Broken part

☐ Tear

☐ Puncture

☐ Corrosion

Severity:

☒ None

☐ Minor

☐ Moderate

☐ Severe

## 4. FINDINGS & ACTION

Damage location  
*None*

Damage extent / dimensions  
*None observed.*

Inspection notes / description:

*All inspected areas are in perfect condition.*

*No scratches, dents, cracks or broken parts found.*

*No damage was recorded during this inspection.*

Recommended action:

*No repair required.*

Driving restriction:

☒ None recorded

☐ Hold for repair

Inspector signature:

*Sam Taylor*

Page 1 of 1