

VEHICLE CONDITION & DAMAGE REPORT

Inspection form VC-01 | Complete all fields and select one box per group.

1. INSPECTION DETAILS

Report reference	Date (YYYY-MM-DD)	Time
VR-0014	2026-09-17	13:30
Inspection site	Inspector name	
West depot	Casey Ellis	

2. VEHICLE IDENTIFICATION

Make	Model	Model year
Seat	Leon	2022
Registration	Colour	Odometer (km)
TST 8669	Green	93,239
Fleet / vehicle reference		
FLEET-0114		

3. CONDITION CHECKLIST

Overall condition: ☒ Perfect ☐ Damage noted

Component inspected	No damage	Damage
Body panels	☒	☐
Front bumper	☒	☐
Rear bumper	☒	☐
Glass / windows	☒	☐
Mirrors	☒	☐
Lights	☒	☐
Wheels / tyres	☒	☐
Interior	☒	☐

Damage type (select one):

☒ None	☐ Scratch	☐ Dent	☐ Crack
☐ Broken part	☐ Tear	☐ Puncture	☐ Corrosion

Severity: ☒ None ☐ Minor ☐ Moderate ☐ Severe

4. FINDINGS & ACTION

Damage location	Damage extent / dimensions
None	None observed.
Inspection notes / description:	
The inspection found the vehicle in perfect condition.	
Exterior and interior are free of visible damage.	
No damage was recorded during this inspection.	
Recommended action:	
No repair required.	
Driving restriction:	☒ None recorded ☐ Hold for repair
Inspector signature:	Casey Ellis